

## Report on the impact of the Niigata-Chuetsu-Oki Earthquake on the Kashiwazaki-Kariwa Nuclear Power Station and response by Tokyo Electric Power Company (TEPCO), national and local governments and other bodies (Progress in July 2007)

Date	TEPCO and other power utilities and JANTI (Japan Nuclear Technology Institute)	National and local government																
Monday July 16, 2007	<p><b>10:13 approx. Earthquake occurs</b></p> <p><b>TEPCO press release: Earthquake update (as at 1 p.m.)</b></p> <ul style="list-style-type: none"> <li>Kashiwazaki-Kariwa nuclear plant reactors 2, 3, 4 and 7 scrambled automatically. Reactors 1, 5 and 6 were already shut down for periodical inspection.</li> <li><b>The fire department confirmed that a fire in the transformer of the No. 3 reactor was brought under control (12:10 p.m.)</b></li> <li>There is no environmental impact from the earthquake and associated fire.</li> </ul>																	
	<p><b>TEPCO press release: Earthquake update (as at 6:30 p.m.)</b></p> <ul style="list-style-type: none"> <li>Several aftershocks were recorded but did not affect any sections of the plant</li> <li>All sections were checked for Departure from Limiting Condition of Operation (LCO) <ul style="list-style-type: none"> <li>Reactors 1, 2 and 3: low water level in spent fuel pool (violation rectified)</li> <li>Reactor 3: Reactor building blow-out panel removed (investigation of violation continuing)</li> <li>Reactors 4, 5, 6 and 7: no violations</li> </ul> </li> </ul>																	
	<p><b>Seismic observation records at the plant (preliminary data)</b></p> <ul style="list-style-type: none"> <li>Recorded earthquake movement provisional values for foundation mat at lowest part of reactor building (with design acceleration response at the same location shown in brackets), in gal</li> </ul> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>Recorded</th> <th>No. 1 reactor</th> <th>No. 5 reactor</th> <th>No. 6 reactor</th> </tr> </thead> <tbody> <tr> <td>Horizontal (N-S)</td> <td>311(274)</td> <td>277(249)</td> <td>271(263)</td> </tr> <tr> <td>Horizontal (E-W)</td> <td>680(273)</td> <td>442(254)</td> <td>322(263)</td> </tr> <tr> <td>Vertical</td> <td>408(235)</td> <td>205(235)</td> <td>488(235)</td> </tr> </tbody> </table>	Recorded	No. 1 reactor	No. 5 reactor	No. 6 reactor	Horizontal (N-S)	311(274)	277(249)	271(263)	Horizontal (E-W)	680(273)	442(254)	322(263)	Vertical	408(235)	205(235)	488(235)	<p><b>Directives from Director of Nuclear and Industrial Safety Agency (NISA) to TEPCO: Analyze seismic observation data and determine impact on earthquake resistance</b></p> <ul style="list-style-type: none"> <li><b>Directed to base the report on the fact that the maximum seismic acceleration recorded at Unit 1, 5 and 6 exceeded the maximum response acceleration</b> based on the base level of seismic motion</li> <li>Analyze seismic observation data from the earthquake</li> <li>Check whether the earthquake has compromised safety of key equipment and facilities</li> </ul>
	Recorded	No. 1 reactor	No. 5 reactor	No. 6 reactor														
Horizontal (N-S)	311(274)	277(249)	271(263)															
Horizontal (E-W)	680(273)	442(254)	322(263)															
Vertical	408(235)	205(235)	488(235)															
<p><b>TEPCO press release: Leakage of radioactive matter from Unit 6</b></p> <ul style="list-style-type: none"> <li>Confirmation of water leakage in uncontrolled areas on 3<sup>rd</sup> level and mid 3<sup>rd</sup> level of reactor chamber (12:50)</li> <li>Confirmation of radiation in water (18:20)</li> <li>Volume of water leak: 3rd level = 0.6 l, approx 2.8 x 10<sup>2</sup> Bq; mid 3rd level = 0.9 l, approx 1.6 x 10<sup>4</sup> Bq</li> <li><b>The water then flowed out to the sea via a discharge outlet (approx. 1.2 m<sup>3</sup>, 6 x 10<sup>4</sup> Bq)</b></li> <li><b>Water is no longer reaching the sea. No significant change in sea level monitor reading, which is below the legislated value</b></li> </ul>	<p><b>Directives from Director of NISA to power utilities: directives to power companies affected by fire and radiation leak</b></p> <ul style="list-style-type: none"> <li><b>Directions to power companies in receipt of directives from the METI Minister regarding unacceptable delays in launching fire-fighting response and in communicating the radiation leak to NISA</b> at the Kashiwazaki-Kariwa nuclear plant</li> <li>Inspection and report on fire-fighting procedures for fires at the nuclear plant</li> <li>Review and report on organization of communication structure between nuclear plant and head office and between head office and the relevant government authorities in regards to incidents such as radiation leaks</li> </ul>																	
Tuesday 17 July		<p><b>NISA press release: Leakage of radioactive material from Unit 6</b></p> <p>NISA response to the report from TEPCO dated July 16 regarding radioactive leak from Unit 6</p> <ul style="list-style-type: none"> <li><b>NISA inspectors confirmed that discharge of radioactive water had ceased, and vindicated TEPCO's original outlook</b></li> <li>TEPCO was ordered to maintain a strict program of monitoring for leakage in the surrounding surveillance area; to put in place a rigid reporting structure; and to identify and rectify the causes</li> </ul>																
	<p><b>TEPCO press release: iodine and other substances detected from main exhaust stack of Unit 7</b></p> <ul style="list-style-type: none"> <li>At approximately 1:00 p.m., <b>iodine and radioactive particulate matter (Cr-51, Co-60) were detected during regular observation of the main exhaust stack</b></li> <li>Total radiation was 3 x 10<sup>8</sup> Bq, dosage was approximately 1.1 x 10<sup>-7</sup> mSv, <b>well below the legally prescribed maximum (1 mSv per individual)</b></li> <li>No significant changes in the main air stack radiation monitor or monitoring post</li> <li>Other exhaust stacks will be monitored</li> </ul>	<p><b>NISA press release: Iodine detected in main air stack of Unit 7</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Cause unknown. Potential causal relationship with earthquake unclear. NISA to launch full investigation</li> </ul>																
	<p><b>TEPCO press release: Earthquake update (as at 5:00 p.m.)</b></p> <p>Unit 1: 8 incidents including: oil leak from exciter transformer (minimal, ongoing); <b>water puddle under damaged fire-fighting pipes (1,670 m<sup>3</sup>)</b></p> <p>Unit 2: 7 incidents including: oil leaking from flange under main transformer (ongoing)</p> <p>Unit 3: 5 incidents including: <b>fire in 3B house transformer (brought under control)</b></p> <p>Unit 4: 3 incidents including: misaligned connecting ducts on main exhaust stack</p> <p>Unit 5: 4 incidents including: water leaking from No. 4 filtrate water tank</p> <p>Unit 6: 3 incidents including: oil leak from low-start transformer B (minimal, ongoing)</p> <p>Unit 7: 3 incidents including: cracks in joints of reinforcement along inlet channel embankment (up to 8 cm in size)</p> <p>Switch yard: 3 incidents including: 500 kV New Niigata 2L shut down</p> <p>Solid waste storage warehouse: <b>Around 100 drums toppled (some with lids open)</b></p> <p>Administration office building: 2 incidents including: normal power supplies shut down</p> <p>Site/other: Seven incidents including: damage to fire-fighting equipment in four locations; water leaks</p>	<p><b>NISA press release: earthquake update</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Council member Kato has today <b>dispatched four more NISA officials</b> to work alongside the inspectors at the site</li> <li><b>TEPCO findings that iodine detected in the main exhaust stack of the Unit 7 has no impact on the surrounding environment were accepted</b></li> <li><b>All values detected at the main exhaust stacks of Unit 1 through 6 were below the minimum requirements</b></li> <li>Instructed to immediately assess the situation with toppled solid waste drums</li> </ul>																



<p>Wednesday 18 July</p>	<p><b>TEPCO press release: Amendment to notification of radiation leak from Unit 6 (dated 16 July)</b></p> <ul style="list-style-type: none"> <li>Discharge out to sea: Amended from <math>6 \times 10^4</math> Bq to <math>9 \times 10^4</math> Bq</li> </ul> <p><b>TEPCO press release: Earthquake update (as at 5:00 p.m.)</b></p> <p>Unit 1 = 9 incidents, Unit 2 = 9 incidents, Unit 3 = 8 incidents, unit 4 = 4 incidents, Unit 5 = 4 incidents, Unit 6 = 3 incidents, Unit 7 = 5 incidents, Switch yard = 3 incidents, Solid waste storage warehouse = 1 issue, Administration office building = 2 incidents, Site/others = 9 incidents</p> <ul style="list-style-type: none"> <li>Observations of the concentration of radioactive matter in the air in the solid waste storage warehouse were taken at four locations. No radioactive matter was detected. Approximately 16 l of water had leaked from the toppled drums, but no radiation was detected. Inspection is continuing</li> </ul>	<p><b>NISA press release: Radiation leak from Unit 6</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO as per amendment</li> <li>TEPCO still maintains that the three-month radioactivity concentration in the surrounding surveillance area is less than 2 in 10 billion Bq/cm<sup>3</sup>, due to dilution of radioactive matter. <b>This figure is a billion times less than the maximum allowable discharge concentration in the surrounding surveillance area over three months (0.2 Bq/cm<sup>3</sup>).</b></li> <li>The error in the announcement on the 16<sup>th</sup> was extremely regrettable</li> <li>A full investigation will be conducted into the source of the calculation error. Faster and more rigorous reporting was ordered.</li> </ul> <p><b>NISA press release: Earthquake update</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Investigations by Mr. Kato and inspectors at the plant are continuing</li> <li><b>Confirmation that radioactive water did not leak from toppled drums</b></li> <li>As yet, no significant directives confirmed for main air stack radiation monitor and monitoring posts</li> </ul> <p><b>Mayor of Kashiwazaki, Hiroshi Aida</b></p> <ul style="list-style-type: none"> <li>Issued direction of <b>emergency prohibition of use of some facilities for all Units at the plant (in relation to dangerous facilities such as outdoor tanks)</b>, in accordance with the Fire Services Law</li> </ul>																																
<p>Thursday 19 July</p>	<p><b>TEPCO press release: Seismic observation records at K-K NPS (subsequent to preliminary data released 16 July)</b></p> <ul style="list-style-type: none"> <li>Data for the earthquake has been collected from all Units</li> <li>Seismic acceleration observations measured at foundation mat at lowest part of reactor building (with design acceleration response at the same location shown in brackets), in gal</li> </ul> <table border="1" data-bbox="311 871 1573 1081"> <thead> <tr> <th>Recorded</th> <th>Unit 1</th> <th>Unit 2</th> <th>Unit 3</th> <th>Unit 4</th> <th>Unit 5</th> <th>Unit 6</th> <th>Unit 7</th> </tr> </thead> <tbody> <tr> <td>Horizontal (N-S)</td> <td>311(274)</td> <td>304(167)</td> <td>308(192)</td> <td>310(193)</td> <td>277(249)</td> <td>271(263)</td> <td>267(263)</td> </tr> <tr> <td>Horizontal (E-W)</td> <td>680(273)</td> <td>606(167)</td> <td>384(193)</td> <td>492(194)</td> <td>442(254)</td> <td>322(263)</td> <td>356(263)</td> </tr> <tr> <td>Vertical</td> <td>408(235)</td> <td>282(235)</td> <td>311(235)</td> <td>337(235)</td> <td>205(235)</td> <td>488(235)</td> <td>355(235)</td> </tr> </tbody> </table> <p><b>TEPCO press release: plant status (as at 5:00 p.m.)</b></p> <p>All facilities have been inspected externally where possible. The results are as follows:</p> <ul style="list-style-type: none"> <li>Reactors 2, 3, 4 and 7 shut down automatically and are now stable in cold shutdown</li> <li>Two incidents involving radioactivity emission <ul style="list-style-type: none"> <li>1) Water leak from Unit 6 discharged into the open seas (July 16 press release) <ul style="list-style-type: none"> <li>Level of radiation discharged into the sea was approximately <math>9 \times 10^4</math> Bq; total radiation exposure was approximately <math>2 \times 10^{-9}</math> mSv (well below the legally prescribed maximum of 1 mSv per individual per year)</li> <li>The SF pool water that flooded into the operating floor of the reactor chamber (a controlled area) is thought to have made its way into the uncontrolled area along the fuel exchanger cables and wire ducts. The cause is still under investigation.</li> </ul> </li> <li>2) Iodine and radioactive particulate matter detected in main exhaust stack monitor of No. 7 reactor (July 17 press release) <ul style="list-style-type: none"> <li>Radiation level detected thus far from the main air stack is approximately <math>4 \times 10^8</math> Bq; total radiation exposure was approximately <math>2 \times 10^{-7}</math> mSv (well below the legally prescribed maximum of 1 mSv per individual per a year)</li> <li>Evaluation of radiation levels continuing</li> </ul> </li> </ul> </li> <li>Main findings identified thus far: <ul style="list-style-type: none"> <li>14 incidents involving radioactive matter: the 2 incidents described above, misaligned connecting ducts on main exhaust stack (Unit 1 through 5), water puddle under damaged fire-fighting pipes (1,670 m<sup>3</sup>) (Unit 1), water on operating floor in reactor building (Unit 1 through 6)</li> <li>53 incidents not involving radioactive matter</li> </ul> </li> </ul>	Recorded	Unit 1	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6	Unit 7	Horizontal (N-S)	311(274)	304(167)	308(192)	310(193)	277(249)	271(263)	267(263)	Horizontal (E-W)	680(273)	606(167)	384(193)	492(194)	442(254)	322(263)	356(263)	Vertical	408(235)	282(235)	311(235)	337(235)	205(235)	488(235)	355(235)	<p><b>Nuclear Safety Commission</b></p> <ol style="list-style-type: none"> <li>Findings from site investigation</li> <li>Impact on the nuclear power station</li> <li>Outbreak of fire in the transformer at Unit 3 and subsequent response</li> </ol> <p><b>&lt;Findings from site investigation&gt;</b></p> <ol style="list-style-type: none"> <li>Investigation conducted by three officials, including acting Chairman Higashi and Mr. Hayata</li> <li>Sites visited: Unit 3 house transformer (fire outbreak), Unit 2 transformer (damage to foundation bolts), No. 6 reactor exhaust stack area (water leak), control room for Unit. 6 and 7, solid waste storage warehouse</li> <li>Observations from Mr. Higashi: <ul style="list-style-type: none"> <li>The No. 7 reactor scram automatically at the time of the earthquake. <b>A readout in the central control room of indicated that the reactor is under cold shutdown. Operators will need to continue checking the reactor core.</b></li> <li>The response to the fire in the transformer at Unit 3 at the time of the earthquake constitutes a key issue. <b>It is important that the lessons learned from this incident are passed on to other power stations.</b></li> <li>Water containing trace levels of radiation spilled from the spent fuel pool of the No. 6 reactor due to major tremors during the earthquake, and also because containment did not function adequately. We were told that it may have reached the uncontrolled area</li> </ul> </li> </ol> <p><b>&lt;Statement from Chairperson Atsuyuki Suzuki&gt;</b></p> <ul style="list-style-type: none"> <li>The power plant is essentially safe. It did not reach a serious state. All operating reactors scrambled automatically as they were designed to do, and the key safety features providing multiple layers of protection from highly radioactive material inside the reactor functioned properly. Nevertheless, the earthquake has had a significant impact on the plant, as exemplified by the transformer fire.</li> <li>The radioactive water leak into the uncontrolled area will be investigated based on reports from operators and government authorities as well as the findings of the Nuclear Safety Commission.</li> <li>According to the Nuclear Safety Commission findings, there are many lessons learned from the transformer fire, with respect to procedures at other nuclear plants and fire-fighting techniques in general. The necessary studies should be carried out as soon as practicable in order to identify the salient issues.</li> <li>We have put in a strong request to the government authorities to instruct the operators to evaluate the impact of the earthquake on the seismic resistance of the plant. The operators will also be asked to perform additional studies to identify the location of the fault line.</li> <li>We will lobby the operators and the government authorities for a thorough investigation in line with the newly amended guidelines with respect to the suitability of the original design and the emergence of new knowledge which was not available at the time.</li> <li>We believe that the back check will demonstrate the validity of the new guidelines for the recent earthquake. Now is not the time to debate the pros and cons of further amendments to the new guidelines. The validity depends on whether the requirements are adequate. We must not make any assumptions.</li> </ul> <p><b>NISA press release: Earthquake update</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Mr. Kato and inspectors at the plant reported <b>no problems with reactor vessels and associated equipment and machinery</b> based on visual inspection</li> <li>As yet, no significant directives confirmed for main air stack radiation monitor and monitoring posts</li> </ul>
Recorded	Unit 1	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6	Unit 7																											
Horizontal (N-S)	311(274)	304(167)	308(192)	310(193)	277(249)	271(263)	267(263)																											
Horizontal (E-W)	680(273)	606(167)	384(193)	492(194)	442(254)	322(263)	356(263)																											
Vertical	408(235)	282(235)	311(235)	337(235)	205(235)	488(235)	355(235)																											

	<p><b>TEPCO press release: Update on investigation into iodine detected in main exhaust stack of Unit 7</b>          &lt;Origin of iodine discharge into the environment&gt;</p> <ul style="list-style-type: none"> <li>• Delay to shut off turbine ground exhaust ventilator after automatic reactor scram</li> <li>• As a result, residual iodine and radioactive particulate matter in the condenser was sucked into the exhaust ventilator and discharged via the exhaust stack. The investigation is continuing.</li> <li>• Analysis of reactor water samples indicates that there was no leakage of radioactive matter from the fuel rods into the reactor water</li> </ul> <p>&lt;Environmental impact&gt;</p> <ul style="list-style-type: none"> <li>• The monitoring frequency for radioactive iodine and particulate matter in the main exhaust stack has been increased from once per week to daily. Atmospheric monitoring in the surrounding surveillance area is also being conducted daily as of July 18 onwards.</li> <li>• Iodine 131 and iodine 133 were detected in the main exhaust stack on July 18, but were not detected in the surrounding surveillance area on July 18 or 19.</li> <li>• The total radiation dose from the main air stack thus far is approximately <math>2 \times 10^{-7}</math> mSv</li> </ul>	<p><b>NISA press release: iodine detected in main exhaust stack of Unit 7 (the second report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers are currently confirming iodine emissions from air stack and reactor water measurements</li> <li>• TEPCO to be instructed to take necessary actions with respect to emission controls</li> </ul>
Friday July 20	<p><b>TEPCO press release: Results of radiation readings from main exhaust stack of Unit 7</b>          Environmental impact</p> <ul style="list-style-type: none"> <li>• Iodine 131 and iodine 133 were detected in the main air stack on July 18, but not on July 19.</li> <li>• The total radiation dose from the main exhaust stack thus far is approximately <math>2 \times 10^{-7}</math> mSv (no change from July 19)</li> <li>• Monitoring for iodine and radioactive matters in the main exhaust stack will be conducted on a daily basis for the immediate future</li> </ul> <p><b>TEPCO press release: Earthquake update (as at 1:00 p.m.)</b>          63 issues confirmed to date (not including the four automatic reactor scrams at the time of the earthquake)</p> <ol style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)             <ul style="list-style-type: none"> <li>- Discharge of water containing radioactive material out to sea (Unit 6)</li> <li>- Iodine and radioactive particulates detected at main exhaust stack monitor (Unit 7)</li> <li>- Misaligned connecting ducts on main exhaust stack (Unit 1 through 5)</li> <li>- Water puddle in combined reactor building from damaged fire-fighting pipes (1,670 m<sup>3</sup>) (Unit 1)</li> <li>- Water puddle on operating floor in reactor building (Unit 1 through 7)</li> </ul> </li> <li>2) Incidents NOT related radioactive materials (52 issues, including the four automatic reactor scram at the time of the earthquake)</li> </ol>	<p><b>NISA press release: Iodine detected in main exhaust of Unit 7 (the third report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers at the plant are currently checking over data for iodine discharge from the air shaft and reactor water measurements. NISA will continue to monitor the situation strictly</li> </ul> <p><b>NISA press conference: Earthquake update (the fourth report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers are currently at the plant:             <ul style="list-style-type: none"> <li>- The data demonstrates that there was no radiation in the collected water that was discovered on the 5<sup>th</sup> floor below ground of the reactor combined building, which had come from damaged fire-fighting pipes in the Unit 1.</li> <li>- Observations data shows that iodine and particulates were not detected in the main exhaust stack of the Unit 7 on July 18 and 19.</li> <li>- NISA officers are present at the TEPCO investigation into the route taken by the water leak in the uncontrolled area of the No. 6 reactor to determine whether TEPCO's assumptions were correct</li> </ul> </li> <li>• There are no significant changes in the main air stack radiation monitor and monitoring posts</li> </ul>

	<p><b>TEPCO press conference: Investigation into fire in the house transformer 3B at Unit 3</b>  Inspection involved mainly above-ground inspection and found the following:</p> <ul style="list-style-type: none"> <li>• The connecting bus line section on secondary side of the transformer had slipped downwards relative to the transformer foundations</li> <li>• The transformer and the connecting bus line on the secondary side are out of vertical alignment</li> <li>• Oil is leaking from the bushing on the transformer secondary side</li> <li>• The fire has caused extensive damage to the connecting ducts of the connecting bus line section on the transformer secondary side; the bus line section is melted and broken in some places</li> <li>• There does not appear to have been any other serious fire-related damage to date</li> </ul> <p><b>TEPCO press release: Reporting on safety levels</b>  Internal investigations are continuing in accordance with the directive from NISA dated July 16. A report of the findings, covering the events, causes and responses, will be submitted to NISA, and preventative measures will be implemented as soon as practicable.  &lt;NISA directive dated July 16&gt;</p> <ol style="list-style-type: none"> <li>1) Investigation of causes why it took so long to deliver the report on the water leakage</li> <li>2) Confirm the response to a transformer fire</li> <li>3) Analyze seismic observation data from the earthquake and check safety (seismic resistance) of key equipment and facilities</li> </ol> <p><b>Power utilities: Report on findings of review of fire-fighting and incident communicating procedures and structures</b>  <b>Report to NISA in response to</b> written directive from NISA dated July 16  &lt;Summary of directive&gt;</p> <ol style="list-style-type: none"> <li>1) Report on an immediate review of fire-fighting procedures and structures in response to the fire at the nuclear power plant</li> <li>2) Report on an immediate review of the communication structure between nuclear plant and head office and between head office and the relevant government authorities in regards to incidents such as radiation leaks</li> </ol>	<p><b>Directive from METI minister to power utilities</b>  <b>Stipulates measures required in order to ensure the safety and security of the people. Details of planned modifications/upgrades in accordance with 1) and 2) below must be submitted by July 26.</b></p> <p><u>1) Upgrade to internal fire-fighting capacity</u></p> <ul style="list-style-type: none"> <li>• Move immediately to put in place a structure designed to facilitate immediate deployment of staff in sufficient numbers in the event of a fire</li> <li>• Maintain chemical fire-fighting vehicles and other equipment required for oil fires</li> <li>• Provide dedicated communication lines for fire-fighting activities</li> <li>• Provide the relevant employees with more opportunity to work closely with fire-fighting services, such as taking part in drills and exercises</li> </ul> <p><u>2) Faster and more rigorous incident communication procedures</u></p> <ul style="list-style-type: none"> <li>• Move immediately to put in place a structure for immediate deployment of staff to check for radioactive leakage in the event of a fire due to earthquake or other cause</li> <li>• Set up robust communication lines designed to withstand the effects of a fire due to earthquake or other cause and enable internal communication and communication between the plant and the emergency headquarters set up by the operator</li> <li>• Inform local and national governments immediately of any confirmed or suspected leakage of radioactive material</li> </ul> <p><u>3) Check earthquake resistance with a view to public safety</u></p> <ul style="list-style-type: none"> <li>• Incorporate new information and insights gained from this incident into ongoing evaluation of earthquake resistance and facility safety levels</li> <li>• Review of the implementation program in order to complete the evaluation as quickly as possible (findings should be made available within one month)</li> </ul> <p><b>METI minister: non-scheduled press conference</b></p> <ul style="list-style-type: none"> <li>• Notwithstanding peripheral facilities and equipment, the key reactors themselves all shut down safely and automatically as designed</li> <li>• Radioactive emissions from the power plant were detected; emissions from the Unit 7 main exhaust stack had ceased as of today. The volume of radiation generated thus far is equivalent to one part in ten million of the volume of radiation that an average person would absorb from natural sources during normal daily activities. Similarly, the radioactive water that leaked from the Unit 6 is equivalent to nine liters of hot water from a radon thermal spring, and will have no impact on the surrounding environment.</li> </ul>																																													
<p>Saturday July 21</p>	<p><b>TEPCO</b></p> <ul style="list-style-type: none"> <li>• <b>Site open to press (Unit 1 Diesel Oil Tank, Unit 3 House Transformer, No.4 Filtered Water Tank and etc.)</b></li> </ul> <p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• 63 issues confirmed to date (not including the four automatic reactor scrams at the time of the earthquake): <b>no additions since July 20</b> <ol style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor scram due to the earthquake)</li> </ol> </li> <li>• <b>An analysis of reactor water from reactors 2 through 7, which were loaded with fuel, indicated no damage to the fuel. It is considered highly unlikely that fuel was damaged by the release of radioactive iodine, for several reasons: the iodine 131 concentration inside the No. 7 reactor was normal at around <math>3 \times 10^{-2}</math> Bq/g during operation; after shutdown it fell to <math>9 \times 10^{-3}</math> Bq/g, according to analysis of reactor water samples; and the high-sensitivity off-gas monitor reading declined after the emergency shutdown due to the earthquake.</b></li> <li>• Summary of increased monitoring for radioactive emissions from the main exhaust stack of Unit 7  &lt;Radioactive iodine and particulate emissions from the main exhaust stack of Unit 7&gt;</li> </ul> <table border="1" data-bbox="385 1396 1430 1591"> <thead> <tr> <th>Sampling period</th> <th>Radioactive iodine</th> <th>Particulate matter</th> </tr> </thead> <tbody> <tr> <td>July 9 – 17</td> <td><math>3 \times 10^8</math> Bq</td> <td><math>2 \times 10^6</math> Bq</td> </tr> <tr> <td>July 17 – 18</td> <td><math>2 \times 10^7</math> Bq</td> <td>Not detected</td> </tr> <tr> <td>July 18 – 19</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>July 19 – 20</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>Total</td> <td><math>4 \times 10^8</math> Bq</td> <td><math>2 \times 10^6</math> Bq</td> </tr> </tbody> </table> <p>&lt;Radioactive iodine and particulate levels at boundaries of surrounding surveillance area&gt;</p> <table border="1" data-bbox="385 1617 1608 1753"> <thead> <tr> <th rowspan="2">Sampling period</th> <th colspan="2">MP-1</th> <th colspan="2">MP-5</th> <th colspan="2">MP-8</th> </tr> <tr> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> </tr> </thead> <tbody> <tr> <td>July 18 – 20</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>July 21</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> </tr> </tbody> </table>	Sampling period	Radioactive iodine	Particulate matter	July 9 – 17	$3 \times 10^8$ Bq	$2 \times 10^6$ Bq	July 17 – 18	$2 \times 10^7$ Bq	Not detected	July 18 – 19	Not detected	Not detected	July 19 – 20	Not detected	Not detected	Total	$4 \times 10^8$ Bq	$2 \times 10^6$ Bq	Sampling period	MP-1		MP-5		MP-8		Iodine	Particulates	Iodine	Particulates	Iodine	Particulates	July 18 – 20	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	July 21	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	<p><b>Niigata Prefectural Government press release: Outcomes from site examination</b></p> <p>Following the site inspection in accordance with the safety agreement (examination team accompanied by members of the Niigata Prefecture Environment Monitoring Council for Nuclear Power Plant Region), a public statement was issued to the effect that the radiation emissions were of such negligible levels as to be completely harmless, with no health effects.</p> <p>&lt;Main items on inspection&gt; Radiation leak in Units No. 6 and No. 7</p> <ul style="list-style-type: none"> <li>• Check radiation measurement data</li> <li>• Inspect affected areas (both restricted and unrestricted) in the No. 6 reactor building</li> <li>• Confirm sampling procedure and measurement points used to monitor radioactive iodine emissions from main exhaust stack of No. 7 reactor</li> <li>• Check radioactivity management at the site, such as definition of protected areas within the power plant</li> </ul> <p>&lt;Feedback from members of the assessment committee &gt;</p> <p>(1) Radioactive material discharged from the Unit No. 6 into the sea</p> <ul style="list-style-type: none"> <li>• The quantity of radiation discharged into the sea is equivalent to that contained in nine liters of hot water from a radon thermal spring</li> <li>• Radiation testing was conducted by prefectural authorities at the No. 6 discharge outlet and five points in the adjoining marine area, but found no radiation attributable to the nuclear plant</li> <li>• The measurement data and radiation management procedures and processes were deemed adequate</li> <li>• Preventative measures have been implemented and there is no danger of further leaks</li> <li>• Water quality in the marine area will be tested another two or three times in order to restore public confidence</li> </ul> <p>(2) Radioactive emissions from the Unit No. 7 main exhaust stack</p> <ul style="list-style-type: none"> <li>• Iodine not detected at any of the three prefectural radiation monitoring posts to date</li> <li>• No radiation detected since TEPCO identified and rectified the problem on July 18</li> <li>• Total radiation up to July 18 was approximately 400 million Bq (= 1.3 mSv per 10,000,000), equivalent to 1/400,000 the level of a chest X-ray, or one ten millionth of the amount that an average person would absorb from the natural environment (2.4 mSv) in other words, extremely low</li> </ul>
Sampling period	Radioactive iodine	Particulate matter																																													
July 9 – 17	$3 \times 10^8$ Bq	$2 \times 10^6$ Bq																																													
July 17 – 18	$2 \times 10^7$ Bq	Not detected																																													
July 18 – 19	Not detected	Not detected																																													
July 19 – 20	Not detected	Not detected																																													
Total	$4 \times 10^8$ Bq	$2 \times 10^6$ Bq																																													
Sampling period	MP-1		MP-5		MP-8																																										
	Iodine	Particulates	Iodine	Particulates	Iodine	Particulates																																									
July 18 – 20	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																																									
July 21	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																																									

Sunday July 22	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>63 issues confirmed to date (not including the four automatic reactor scrams due to the earthquake): <b>no additions since July 20</b></li> </ul> <table border="1"> <tr><th colspan="3">&lt;Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack&gt;</th></tr> <tr><td>Sampling period</td><td>Radioactive iodine</td><td>Particulate matter</td></tr> <tr><td>July 20 – 21</td><td>Not detected</td><td>Not detected</td></tr> <tr><td>Total (July 9 – 21)</td><td>4 x 10<sup>8</sup> Bq</td><td>2 x 10<sup>6</sup> Bq</td></tr> </table> <table border="1"> <tr><th colspan="7">&lt;Radioactive iodine and particulate levels at boundaries of surrounding surveillance area&gt;</th></tr> <tr><th rowspan="2">Sampling period</th><th colspan="2">MP-1</th><th colspan="2">MP-5</th><th colspan="2">MP-8</th></tr> <tr><th>Iodine</th><th>Particulates</th><th>Iodine</th><th>Particulates</th><th>Iodine</th><th>Particulates</th></tr> <tr><td>July 22</td><td>Not detected</td><td>Not detected</td><td>Not detected</td><td>Not detected</td><td>Not detected</td><td>Not detected</td></tr> </table>	<Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack>			Sampling period	Radioactive iodine	Particulate matter	July 20 – 21	Not detected	Not detected	Total (July 9 – 21)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	<Radioactive iodine and particulate levels at boundaries of surrounding surveillance area>							Sampling period	MP-1		MP-5		MP-8		Iodine	Particulates	Iodine	Particulates	Iodine	Particulates	July 22	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	<p><b>Governor of Niigata Prefecture Hirohiki Izumida</b></p> <ul style="list-style-type: none"> <li>Submits written request to national government regarding examination by IAEA group</li> <li>“This incident has damaged local industry through rumor-mongering. In order to restore public confidence, <b>we must provide the outside world with full and accurate information</b>”</li> </ul> <p><b>Niigata Prefectural Government website: Radiation monitoring information (the first report)</b></p> <p>To the people of Kashiwazaki-Kariwa</p> <ul style="list-style-type: none"> <li><b>Radiation emissions from the No. 7 reactor</b> at the Kashiwazaki-Kariwa nuclear power station <b>ceased on the 18<sup>th</sup></b></li> <li><b>The radiation dosage from emissions between the 16<sup>th</sup> and the 18<sup>th</sup> is equivalent to approximately 1/400,000 of the radiation exposure in a standard chest X-ray</b>, and has no effect on human health</li> <li>Monitoring conducted by the Niigata Prefectural Government <b>has detected no radiation emissions from the power plant since the earthquake</b>. There is therefore no cause for alarm.</li> </ul>
<Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack>																																									
Sampling period	Radioactive iodine	Particulate matter																																							
July 20 – 21	Not detected	Not detected																																							
Total (July 9 – 21)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																																							
<Radioactive iodine and particulate levels at boundaries of surrounding surveillance area>																																									
Sampling period	MP-1		MP-5		MP-8																																				
	Iodine	Particulates	Iodine	Particulates	Iodine	Particulates																																			
July 22	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																																			
Monday July 23	<p><b>TEPCO press release: Radiation measurements at the main exhaust stack of Unit 7 for July 22</b></p> <table border="1"> <tr><th colspan="3">&lt;Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack&gt;</th></tr> <tr><td>Sampling period</td><td>Radioactive iodine</td><td>Particulate matter</td></tr> <tr><td>July 21 – 22</td><td>Not detected</td><td>Not detected</td></tr> <tr><td>Total (July 9 – 22)</td><td>4 x 10<sup>8</sup> Bq</td><td>2 x 10<sup>6</sup> Bq</td></tr> </table> <p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>63 issues confirmed to date (not including the four automatic reactor scrams due to the earthquake): <b>no additions since July 20</b></li> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor scrams due to the earthquake)</li> <li><b>The amount of puddle on the 5<sup>th</sup> floor below ground of the reactor combined building. 1,670m<sup>3</sup> ==&gt; 2,000m<sup>3</sup></b></li> <li><b>Radiation was not detected during regular testing for radioactive emissions at the main exhaust stacks of the Unit 1, 2 and 6. Unit 3, 4 and 5 will be tested tomorrow.</b></li> </ul> <p><b>TEPCO press release: Investigation into leakage of radioactive matter in Unit 6</b></p> <p>Following a thorough investigation, <b>the water leak in the uncontrolled areas on the 3<sup>rd</sup> and mid 3<sup>rd</sup> levels of the reactor building was attributed to the following factors.</b></p> <ul style="list-style-type: none"> <li>Water overflowed from the spent fuel pool on the operating floor on the 4<sup>th</sup> level of the reactor building and entered the fuel exchanger power supply box on the same floor, where it got into a cable duct via gaps in the seal around the cable passages in the box.</li> <li>The water traveled through embedded the cable duct, and dripped from upper air conditioning ducts on the mid 3<sup>rd</sup> level of the reactor building. It also dripped from openings in the mid 3<sup>rd</sup> level floor down to the 3<sup>rd</sup> level floor.</li> <li>Puddle on the 3<sup>rd</sup> level floor surface drained out through drain outlets into a non-radioactive wastewater tank in the basement level. From here, it was sent out to sea via discharge outlets</li> </ul> <p><b>JANTI: On-site investigation (the team of 3 members) — until 24 July</b></p>	<Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack>			Sampling period	Radioactive iodine	Particulate matter	July 21 – 22	Not detected	Not detected	Total (July 9 – 22)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	<p><b>NISA press release: Earthquake update (the fifth report)</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li><b>NISA Chairman Mr. Komoda visited Niigata prefecture today and met with the governor of Niigata prefecture, the mayor of Kashiwazaki City and the mayor of Kariwa town to discuss the NISA response to the incident</b></li> <li>NISA officers are currently at the plant: <ul style="list-style-type: none"> <li>The data demonstrates that no iodine or particulates have been detected in the main air stack of the No. 7 since July 18.</li> <li>With respect to the leakage of radioactive material from the Nos. 6 and 7 reactors, NISA will be present at the TEPCO investigation into the route taken by the water leak to determine whether the suspected route initially announced by TEPCO was correct</li> </ul> </li> <li>There are no significant changes in the main air stack radiation monitor and monitoring posts</li> </ul> <p><b>METI Vice Minister, Kitabatake: regular press conference</b></p> <ul style="list-style-type: none"> <li><b>In light of the growth of nuclear power throughout the world, it is most important to provide safety information about nuclear power around the world via the medium of the IAEA, and to share information about strategies and initiatives.</b> To this end, <b>the Ministry has formally notified the IAEA today</b> that its staffs will be permitted to visit the Kashiwazaki-Kariwa nuclear power plant in Japan.</li> </ul>																											
<Radioactive iodine and particulate emissions from Unit No. 7 main exhaust stack>																																									
Sampling period	Radioactive iodine	Particulate matter																																							
July 21 – 22	Not detected	Not detected																																							
Total (July 9 – 22)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																																							
Tuesday July 24	<p><b>TEPCO press release: Radiation readings at the main exhaust stack of the Unit 7 for July 23</b></p> <table border="1"> <tr><th colspan="3">Radioactive iodine and particulate emissions from Unit 7 main exhaust stack</th></tr> <tr><td>Sampling period</td><td>Iodine</td><td>Particulates</td></tr> <tr><td>July 22 – 23</td><td>Not detected</td><td>Not detected</td></tr> <tr><td>Total (July 9 – 23)</td><td>4 x 10<sup>8</sup> Bq</td><td>2 x 10<sup>6</sup> Bq</td></tr> </table> <p><b>TEPCO press release: Earthquake update (as at 2:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>In addition to the 63 issues confirmed to date (which excludes the four automatic reactor scrams at the earthquake), <b>we have confirmed damage to drive shaft joints on a ceiling crane in the No. 6 reactor building</b></li> <li><b>Radiation monitoring in the main exhaust stack was conducted at Unit 3, 4 and 5 but no radioactive material was detected</b></li> </ul>	Radioactive iodine and particulate emissions from Unit 7 main exhaust stack			Sampling period	Iodine	Particulates	July 22 – 23	Not detected	Not detected	Total (July 9 – 23)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	<p><b>Minister of Economy, Trade and Industry Akira Amari: press conference following Cabinet meeting</b></p> <ol style="list-style-type: none"> <li>Committee set up to investigate effect of the Chuetsu offshore earthquake on the nuclear power plant <ul style="list-style-type: none"> <li>The Committee, <b>acting from the perspective of a third party, will conduct an in-depth examination of the background to incidents</b> such as the transformer fire and emissions of radioactive materials from the power plant, and will <b>use this to identify future issues to be addressed by the national government and operators of nuclear plants</b>. The Committee will be headed by Professor Haruki Madarame from Tokyo University, and will report to the Nuclear Safety and Security Chapter of the Resources and Energy Study Group</li> </ul> </li> <li>IAEA delegation <ul style="list-style-type: none"> <li>Last week the IAEA requested access for a joint study mission. Our response is that <b>Japan believes the international sharing of information to be beneficial</b></li> <li><b>Proposals from Japan:</b> <ul style="list-style-type: none"> <li>IAEA delegation will be permitted to investigate the site</li> <li>The incident will be discussed at the IAEA General Conference in September with senior officials from regulatory bodies around the world</li> <li>Japan will host an international workshop composed of expert consultants from around the world</li> </ul> </li> </ul> </li> </ol> <ul style="list-style-type: none"> <li>We will continue to release information about the impact on the nuclear power plant <b>in clear and simple language in order to restore the confidence of local communities</b></li> </ul>																											
Radioactive iodine and particulate emissions from Unit 7 main exhaust stack																																									
Sampling period	Iodine	Particulates																																							
July 22 – 23	Not detected	Not detected																																							
Total (July 9 – 23)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																																							

<p>Wednesday July 24</p>		<p><b>NISA press release: Earthquake update (6<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (as per left-hand column)</li> <li>• TEPCO reports that since radiation has not been detected in the <b>main air stack of the Unit 7</b> since July 19, the <b>measurement frequency will revert to weekly rather than daily</b> as at present.</li> <li>• NISA inspectors are currently inspecting the damage to the No. 6 ceiling crane</li> <li>• <b>TEPCO is currently preparing to evacuate the water</b> that has collected on the B5 level of the No. 1 reactor combination building, by <b>transferring water from the Unit 1 tank to the Unit 2</b>. NISA inspectors are supervising the use of temporary pools, pumps and hoses at the B5 level of the composite building, the underground tunnel connecting Unit 1 and 2, and Unit 2 waste treatment facility.</li> <li>• NISA inspectors were present at <b>helium gas tests to determine the route taken</b> by radiation that leaked from the Unit 6</li> <li>• No other significant developments in main exhaust stack radiation monitor and monitoring posts.</li> </ul>
	<p><b>TEPCO</b></p> <ul style="list-style-type: none"> <li>• <b>No. 6 reactor building and the turbine building operating floor (gallery room) opened to the media</b></li> </ul>	<p><b>Niigata Prefectural Government website: Radiation monitoring information (the second report)</b></p> <ul style="list-style-type: none"> <li>• <b>No radiation has been detected in crops, livestock and marine produce sourced from the general area of the nuclear power plant</b></li> <li>• <b>Fish and vegetables from Niigata prefecture</b> are delicious as always and safe to eat</li> <li>• <b>The radiation leak</b> from the nuclear power plant on July 21 <b>has been investigated in conjunction with radiation experts</b></li> <li>• <b>The level of radiation emissions was extremely small, with no effect on human health</b></li> </ul>
	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• <b>Results of external inspection conducted after earthquake:</b> 63 issues have been confirmed to date (not including the four automatic reactor scram due to the earthquake) <ul style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor shutdowns at the time of the earthquake)</li> </ul> </li> <li>• <b>Results of follow-up inspection:</b> one issue (damage to drive shaft joints on a ceiling crane in the No. 6 reactor building)</li> <li>• <b>Scheduled manual startup testing was performed on one of the three emergency diesel generators in each of the No. 1, 2, 5 and 7 reactors without error. Diesel generators in the No. 3, 4 and 6 reactors will be tested today.</b></li> </ul>	<p><b>NISA press release: Acknowledgement of accident and failure report and earthquake update (7<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>• NISA has received the Accident and Failure Report from TEPCO, along with an update on conditions at the plant</li> <li>• Mr. Kato returned to the plant today for a further inspection together with NISA officials. The inspection covered the scheduled manual testing of emergency diesel generators. No issues have been identified today.</li> <li>• The team is also inspecting the water in the B5 level of the No. 1 reactor combination building and the damage to drive section of the ceiling crane in the No. 6 reactor building.</li> <li>• No other significant developments in the main air stack radiation monitor and monitoring posts.</li> </ul>
<p>Thursday July 25</p>	<p><b>TEPCO press release: Submission of report on nuclear plant accident and failure report and electrical damage report</b></p> <ul style="list-style-type: none"> <li>• Water containing radioactive material leaked into an unrestricted zone in the No. 6 reactor building (Operating Regulations Article 19, Paragraph 17, Item 9)</li> <li>• Water spilled on the operating floors of Nos. 1 through 7 reactor buildings (Operating Regulations Article 19, Paragraph 17, Item 10)</li> <li>• Damage was sustained to drive shaft joints on a ceiling crane in the No. 6 reactor building (Operating Regulations Article 19, Paragraph 17, Item 3)</li> <li>• A fire occurred in the transformer (B) in the Unit No. 3 (Reporting Regulations on Electrical Incidents Article 3, Part 1, Item 3)</li> </ul>	<p><b>NISA press release: safety check</b></p> <p>&lt;Manual startup test on emergency diesel generators&gt;</p> <ul style="list-style-type: none"> <li>• Manual startup tests were performed on <b>seven emergency diesel generators today. All satisfied the safety criteria.</b></li> <li>• NISA will continue monitoring testing of the remaining emergency diesel generators to be completed by July 27.</li> </ul> <p>&lt;Confirmation of flooding on B5 level of No. 1 reactor combination building caused by damage to fire protection system piping.&gt;</p> <ul style="list-style-type: none"> <li>• Flooding on the B5 level of the reactor combination building entered the restricted area. As such, NISA believes that the water should be treated as radioactive, irrespective of whether radiation monitoring shows the levels to be below the detection limit.</li> <li>• A system of pumps and hoses will be used to pump water from the waste output tank at the Unit 1 to the waste output tank at the Unit 2. The transfer process will be checked by inspectors when appropriate.</li> </ul> <p>&lt;Confirmation of damage to drive shaft joints in ceiling crane in No. 6 reactor building&gt;</p> <ul style="list-style-type: none"> <li>• <b>Issued order for immediate check for similar damage to cranes in other reactor buildings.</b> Further investigation is required to identify causes of damage and prevent reoccurrence</li> </ul> <p>&lt;Radioactivity monitoring&gt;</p> <ul style="list-style-type: none"> <li>• NISA has questioned TEPCO regarding assessment of radiation exposure to workers since the day of the earthquake (July 16). NISA is satisfied that TEPCO is managing this area appropriately.</li> <li>• NISA will continue to monitor radiation exposure assessment procedures as necessary.</li> </ul>

<p>Friday July 26</p>	<p><b>TEPCO press release: Geological survey in surrounding marine area</b></p> <ul style="list-style-type: none"> <li>• Insights from the Chuetsu offshore earthquake will be incorporated into an evaluation of anti-earthquake safety standards at the Kashiwazaki-Kariwa nuclear plant <ul style="list-style-type: none"> <li>• <b>The seismic design of the power plant is based on detailed studies of the surrounding land and sea areas conducted at the time of the original construction application</b></li> </ul> </li> <li>• <b>Sonic marine surveying will be conducted as part of geological studies of the sea area in the vicinity of the plant to evaluate the recent seismic behavior including aftershocks</b></li> </ul>	
	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• All plants are shut down and stable at present. There are no significant changes in real-time data for the main air stack radiation monitor and monitoring posts. There is no radiation impact on the surrounding environment.</li> <li>• Plant update <ul style="list-style-type: none"> <li>&lt;Results of external inspection conducted after earthquake&gt; 63 issues have been confirmed to date (not including the four automatic reactor shutdowns at the time of the earthquake) <ol style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor shutdowns at the time of the earthquake)</li> </ol> </li> <li>&lt;Results of follow-up inspection&gt; one issue (damage to drive shaft joints on a ceiling crane in the No. 6 reactor building)</li> </ul> </li> <li>• <b>Scheduled manual startup tests were performed on the second emergency diesel generator in each of the No. 1, 2, 5 and 7 reactors without error. The same tests will be performed at the No. 3, 4 and 6 reactors today.</b></li> <li>• <b>The following issues, attributable to rain, have been confirmed. No radiation has been detected.</b> <ul style="list-style-type: none"> <li>- Water has been discovered on the floor of in the low-pressure condensing pump room on the B2 level of the No. 1 turbine building. This is believed to be rainwater that has entered the B1 level via a connecting corridor between the turbine building and the auxiliary building (and possibly from other points), and then flowed down to the B2 level. </li> <li>- A water leak has been discovered in the wall of the south corridor on the B1 level of the No. 3 turbine building. It is believed that the water has collected in the pit adjoining the turbine building, then traveled along wiring tunnels into the turbine building.</li> <li>- Water has been discovered on the floor of the B1 level of the solid waste storage warehouse in the vicinity of the boundary between the No. 1 building and the administration building. It is believed to be rainwater which has been absorbed into the ground and subsequently risen up.</li> <li>- Water has been discovered on the floor of the B1 level of the auxiliary building. It is believed to be rainwater which has been absorbed into the ground and subsequently risen up.</li> </ul> </li> </ul>	<p><b>METI press release: Establishment of Committee to Investigate Impact of Chuetsu-Oki earthquake on Nuclear Power Plant Facility (provisional title)</b></p> <p>The Committee investigation will <b>examine in depth</b> the effects of the Chuetsu-Oki earthquake on the Kashiwazaki-Kariwa nuclear plant and report to <b>the national government and the operator of the plant on future actions and other considerations</b></p> <p>&lt;Specific issues to be examined&gt;</p> <ol style="list-style-type: none"> <li>1) Adequacy of internal fire protection procedures at the time of the earthquake, as well as reporting and liaison structures and information disclosure to local communities</li> <li>2) Evaluation of seismic safety standards at the plant in light of outcomes from the Chuetsu-Oki earthquake</li> <li>3) Operational procedures and equipment and facility safety at the plant at the time of the Chuetsu-Oki earthquake</li> </ol>
	<p><b>Power utilities: Submission of upgrade programs for internal fire protection systems and incident reporting structures</b></p> <p>Upgrade programs to be submitted in accordance with a directive from the Ministry of the Economy, Trade and Industry (METI) dated July 20 (parts 1) and 2) only at this stage)</p> <p>Requirements of METI directive</p> <ol style="list-style-type: none"> <li>1) Strengthening of internal fire protection systems</li> <li>2) Faster and more accurate incident communication</li> <li>3) Assessment of seismic safety standards predicated on public welfare</li> </ol> 	<p><b>NISA press release: Earthquake update (8<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (as per column on the left)</li> <li>• Mr. Kato and the NISA inspectors continued today with their on-site investigations; <b>they witnessed scheduled manual testing of emergency diesel generators and reported no errors.</b></li> <li>• They also inspected the site of the <b>flooding</b> that was confirmed today, and confirmed that <b>no radiation was detected.</b> TEPCO was instructed to identify and repair the sources of the leakage.</li> <li>• No other significant developments in the main air stack radiation monitor and monitoring posts.</li> </ul>
	<p><b>NISA press release: safety checks</b></p> <p>&lt;Manual startup tests on emergency diesel generators&gt;</p> <ul style="list-style-type: none"> <li>• Manual startup tests were performed on <b>seven emergency diesel generators today, and all satisfied the safety criteria</b></li> <li>• NISA will monitor manual startup tests to be performed on the remaining six emergency diesel generators on July 27</li> </ul> <p>&lt;Water leak (suspected rainwater)&gt;</p> <ul style="list-style-type: none"> <li>• The newly discovered leaks are believed to be primarily the result of earthquake damage to pipe tunnels leading into the building. <b>TEPCO was instructed to identify the entry route and repair and/or rectify as necessary</b></li> </ul> <p>&lt;Damage to drive shaft joints on ceiling crane in reactor building&gt;</p> <ul style="list-style-type: none"> <li>• In light of confirmed damage to the drive shaft joints of the ceiling crane in the No. 6 reactor building, <b>the drive shaft joints of the ceiling cranes in the No. 2 and No. 3 reactor buildings were also inspected</b></li> <li>• There were no safety issues according to the on-site inspectors. The remaining ceiling cranes will be inspected in due course.</li> </ul>	
	<p><b>NISA press release</b></p> <ul style="list-style-type: none"> <li>• NISA today received reports of upgrade programs from nuclear plant operators in relation to 1) Strengthening of internal fire protection systems and 2) Faster and more accurate incident reporting in accordance with the Ministerial directive dated July 20.</li> <li>• A Working Group on disaster response procedures will be set up within the Committee to Investigate Impact of Chuetsu-Oki earthquake on Nuclear Power Plant Facility in conjunction with the Fire and Disaster Management Agency (FDMA). The sub-committee will take three months to investigate internal fire protection systems and reporting and liaison structures. The recommendations from the sub-committee will be expected to contribute to improvement of the emergency response programs of power utilities.</li> </ul>	

Friday July 27	<p><b>TEPCO website</b> Presentation of <i>Impact of Niigata Chuetsu Earthquake on Nuclear Plant</i> with photographs, describing reactors and other facilities and equipment</p>	<p><b>Nuclear Safety Commission secretariat: Nihon Keizai Shimbun newspaper article</b> The Nuclear Safety Commission wishes to refute claims made in an article which appeared in today's edition of the Nihon Keizai Shimbun newspaper, entitled <i>Tougher Seismic Protection Standards Nuclear Safety Commission demands Mandatory Disclosure of Major Failure Risk</i>. The Nuclear Safety Commission has made no such demand. &lt;Summary of article&gt; The national Nuclear Safety Agency on July 26 resolved to amend guidelines for seismic design standards at nuclear power plants. The revised guidelines will require disclosure of the estimated risk of occurrence of major failures, together with associated remedial work to minimize the risks. The Nuclear Safety Commission plans to introduce the amendments in FY2008.</p>
	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>Manual startup tests were performed on 20 of the emergency diesel generators in Units 1 through 7, with no errors reported</li> <li>Update on impact of rainwater in restricted area <ul style="list-style-type: none"> <li>&lt;No. 1 turbine building&gt; On July 26, water was pumped from the low-pressure condensing pump room on the B2 level of the No. 1 turbine building and into the waste treatment system On July 27 it was confirmed that there was no water in the B1 level of the turbine building. However, water is continuing to trickle in from the connecting corridor between the turbine building and the auxiliary building</li> <li>&lt;No. 3 turbine building&gt; On July 26, the water was removed. On July 27, it was confirmed that there was no more water leaking into the turbine building.</li> <li>&lt;Solid waste storage facility&gt; On July 26, removal of water was completed. On July 27, it was confirmed that there was no more water leaking into the facility.</li> <li>&lt;Auxiliary building&gt; On July 27, it was confirmed that there was no more water leaking into the turbine building.</li> </ul> </li> <li>All plants are shut down and stable at present. There are no significant changes in real-time data for the main air stack radiation monitor and monitoring posts. There is no radiation impact on the surrounding environment.</li> </ul>	<p><b>NISA press conference: Earthquake update (9<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see column on left)</li> <li>NISA officers attended the scheduled manual startup tests of all except one of the emergency diesel generators and confirmed that all operated as normal and satisfied the NISA requirements</li> <li>In light of confirmed damage to the drive shaft joints on a ceiling crane in the No. 6 reactor building, we have inspected the Nos. 1, 2 and 3 reactors, finishing today, and have found no problems</li> <li>No other significant developments in the main air stack radiation monitor and monitoring posts</li> </ul>
	<p><b>TEPCO press release: Results of regular manual startup tests on diesel generators</b></p> <ul style="list-style-type: none"> <li>Manual startup tests were conducted on emergency diesel generators in the Nos. 1 through 7 on July 25 – 27</li> <li>The scheduled tests were completed at 3:19 p.m. today with all equipment confirmed in good working order</li> </ul>	<p><b>NISA press release: negative impact of overseas reporting of the incident</b></p> <p>The government has taken the following steps to address the negative impact of overseas reporting of the incident</p> <ul style="list-style-type: none"> <li>In order to address misperceptions created by inaccurate reporting by some overseas media outlets on the incident at the Kashiwazaki-Kariwa nuclear power plant, the government on July 26 directed that information be provided via the Ministry of Foreign Affairs to its diplomatic establishments abroad for distribution to the governments of all major nations and in particular those nations where inaccurate reporting has occurred</li> </ul>
	<p><b>TEPCO press release: Executive Vice-President relocates to Kashiwazaki-Kariwa region</b></p> <ul style="list-style-type: none"> <li>TEPCO Executive Vice-President Ichiro Takekuro will relocate to the Kashiwazaki-Kariwa area near the plant from July 30 in order to coordinate the response</li> </ul>	<p><b>Ministry of Foreign Affairs website: Impact of earthquake at the Kashiwazaki-Kariwa nuclear power plant</b></p> <p>The following information has been posted in Japanese and English on the Ministry of Foreign Affairs website:</p> <ul style="list-style-type: none"> <li>The recent major earthquake triggered a fire at an electrical transformer in the Kashiwazaki-Kariwa Nuclear Power Plant</li> <li>However, there was no problem with regard to the safety of the nuclear reactors because the reactors which were running at the time of the earthquake were all shut down automatically by safety mechanisms.</li> <li>As a result of the earthquake, a negligible amount of radioactive material was released from the Unit No 7 into the atmosphere, while water containing radioactive material was released from the Unit No 6 into the sea. In both cases, the radioactivity levels were well under the legal safety standards, and there was no impact whatsoever on the surrounding environment. The leaks have already been stopped.</li> <li>Unfortunately, certain news media have created misperceptions through inaccurate and/or inappropriate reporting of the situation, which has adversely affected tourism and other industries in Japan.</li> <li>Japan has provided relevant information to the International Atomic Energy Agency (IAEA) since the incident and, in a bid to promote international cooperation in the field of nuclear safety, has agreed to admit a team from the IAEA for the purpose of conducting a joint examination which will provide objective proof of the current safety of the Kashiwazaki-Kariwa Nuclear Power Plant, boost transparency in the domestic nuclear energy industry, and enable lessons learned from the earthquake to be shared among the international community.</li> </ul>



Monday July 30	<p><b>TEPCO press release: Earthquake update (as at 2:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• Regular monitoring of radiation levels at the main air stack was conducted at the No. 1, 2 and 6 reactors and no radioactive matter was detected (July 23 – 30)</li> <li>• All plants are shut down and stable at present. There are no significant changes in real-time data for the main air stack radiation monitor and monitoring posts. There is no radiation impact on the surrounding environment.</li> </ul>	<p><b>NISA press release: Earthquake update (10<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see column on left)</li> <li>• NISA officers are currently confirming details of the TEPCO plant study such as causal factors and other matters</li> <li>• No other significant developments in the main air stack radiation monitor and monitoring posts</li> </ul>
	<p><b>TEPCO press release: Analysis of seismic observation data (1<sup>st</sup> report)</b></p> <p>We studied seismic observation data on the Chuetsu-Oki earthquake in accordance with the written directive received from NISA on July 16. A report of the analysis findings to date with respect to analysis of the seismic observation data generated in the main earthquake (the 1<sup>st</sup> report) was today submitted to NISA.</p>	<p><b>NISA press release: Analysis of seismic observation data (Part 1)</b></p> <ul style="list-style-type: none"> <li>• NISA has received from TEPCO the first report of the analysis of seismic observation data from the Chuetsu-Oki earthquake in accordance with the directive dated July 16</li> <li>• NISA will scrutinize the report thoroughly in conjunction with expert consultants</li> </ul>

We will continue gathering data records for the aftershocks. This data will be analyzed to evaluate the safety of key equipment and facilities.

<NISA directive (July 16)>

- Analyze seismic observation data for the earthquake
- Evaluate safety levels of key safety-related equipment and facilities

<Summary of report>

1) Observation records

- Examples of acceleration time history waveforms for foundations of Nos. 1 through 7 reactor buildings
- Sample comparison of floor response spectrum based on observation records versus floor response spectrum based on seismic ground motion as per seismic response analysis model used at the original design stage for foundations of Nos. 1 through 7 reactor buildings

2) Analysis of seismic observation data

We will continue gathering data records for the aftershocks. This data will be analyzed to determine seismic motion in relation to evaluation of seismic protection during the earthquake, and to determine seismic motion in the free rock surface (excluding the effect of the upper foundations)

3) Seismic protection for key safety-related equipment and facilities

The seismic motion figures used in the safety evaluation will be used to analyze seismic response and seismic protection of key safety-related equipment and facilities

4) Seismic protection assessment in future

Information obtained through an investigation into active fault lines in the marine area and analyses of seismic observation data will be used to identify potential improvements and modifications to seismic protection assessment and strategies in future

Table: Seismic acceleration observations (with design acceleration response at the same location shown in brackets)

Observation Spot			Seismic acceleration (with design acceleration response at the same location shown in brackets), in gal			Notes
			S-N	E-W	Vertical	
Unit 1	Reactor Building	2F B5F(on the foundation mat)	599(460) 311(274)	884(463) 680(273)	394 408	
	Turbine Building	1F(pedestal)	1862(274)	1459(274)	741	
Unit 2	Reactor Building	2F 517(271)	517(271)	718(271)	412	
		B5F(on the foundation mat)	304(167)	606(167)	282	
	Turbine Building	1F 1F(pedestal) B3F(on the foundation mat)	431(295) 642(588) 387(233)	764(259) 1159(478) 681(232)	594 650 470	
Unit 3	Reactor Building	2F B5F(on the foundation mat)	525(314) 308(192)	650(309) 384(193)	518 311	
	Turbine Building	1F(pedestal) B3F(on the foundation mat)	1350(854) 581(239)	2058(834) 549(243)	619 513	
Unit 4	Reactor Building	2F B5F(on the foundation mat)	606(299) 310(193)	713(293) 492(194)	548 337	
		Turbine Building	1F 1F(pedestal) B3F(on the foundation mat)	411(269) 614(832) 348(238)	560(267) 763(838) 442(242)	549 526 443
	Reactor Building	3F B4F(on the foundation mat)	472(354) 277(249)	697(350) 442(254)	331 205	
Unit 5	Turbine Building	2F(pedestal)	1166(995)	1157(754)	533	
	Unit 6	Reactor Building	3F B3F(on the foundation mat)	554(415) 271(263)	545(411) 322(263)	578 488
Unit 7		Reactor Building	3F B3F(on the foundation mat)	367(415) 267(263)	435(411) 356(263)	464 355
	Turbine Building		2F 2F(pedestal) B2F(on the foundation mat)	418(394) 673(1096) 318(299)	506(418) 1007(859) 322(312)	342 362 336

**Nuclear Safety Commission**

The Nuclear Safety Commission today approved an Opinion Statement on the Impact of the Earthquake and Future Actions as follows:

<New Seismic Guidelines>

Any decision about reviewing the new seismic guidelines should be made on the basis of an evaluation of the impact of the recent earthquake using the seismic motion stated in the new seismic guidelines in accordance with the back check procedure. We are not able to give a decision at this stage.

<Load-bearing performance of buildings and structures>

- The new seismic guidelines state that buildings and structures must be erected on solid foundations to provide adequate load-bearing performance. This applies to all buildings and structures (not just key buildings and structures as in the previous seismic guidelines.)
- There are a number of instances where the earthquake has caused serious damage to equipment, machinery, pipes and ducts, generally due to uneven subsidence of foundations.
- For this reason, it is considered necessary to assess the load-bearing performance of foundations with respect to conformance with the new principles, for B and C classes as well as S class, and to carry out reinforcement work where necessary as determined on the basis of the assessment

<Residual risk evaluation>

Much of the residual risk PSA process is predicated on evaluations that are yet to be performed. The Nuclear Safety Commission will ask the operator to perform quantitative evaluation on a trial basis and will conduct its own investigation with a view to introducing residual risk PSA at some point in the future.

<Upgrading of earthquake-related fire protection systems>

- The Fire Protection System Guidelines from the Nuclear Safety Commission require fire protection systems to be designed so that they can continue functioning in the event of simultaneous earthquake and fire outbreak
- Given that fire protection systems did not function properly in the recent earthquake, we will investigate the level of adherence to the guidelines and consider upgrades to the fire protection system

<p>Tuesday July 31</p>	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• In new developments, <b>thin oil films have been confirmed on the No. 1 turbine building sub-drain and the discharge outlets for the Nos. 1 – 4 reactors.</b> Fluid discharge out the sub-drain has been stopped and <b>a temporary tank is being prepared.</b> Oil film at the discharge outlets is being monitored continuously while the sub-drain is stopped.</li> <li>• <b>Scheduled radiation monitoring of the main exhaust stack was conducted on the Units No. 3, 4, 5 and 7 and no radioactive matter was detected.</b> (No. 3, 4 and 5 reactors: July 24 – 31; No. 7 reactor: July 23 – 31)</li> <li>• All plants are shut down and stable at present. There are no significant changes in real-time data for the main exhaust stack radiation monitor and monitoring posts. There is no radiation impact on the surrounding environment.</li> </ul>	<p><b>NISA press release: Earthquake update (11<sup>th</sup> report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (as per column on left)</li> <li>• Safety inspectors are currently investigating the causes and other details at the plants based on TEPCO findings</li> <li>• There are no significant changes in the main exhaust stack radiation monitor and monitoring posts at present</li> </ul> <p><b>First meeting of the Committee to Investigate the Impact of the Chuetsu-Oki earthquake on the Nuclear Power Plant Facility</b></p> <p>The Working Groups have been set up to investigate specific areas as listed below. The Committee will deliberate on the basis of their reports.</p> <ol style="list-style-type: none"> <li><b>1) Internal fire protection procedures at the time of the earthquake, reporting and liaison structures, and information disclosure to local communities</b> <ul style="list-style-type: none"> <li>&gt;&gt; Working Group to investigate internal fire protection procedures and reporting and liaison structures at the nuclear power plant in the event of the Chuetsu offshore earthquake (provisional title)</li> <li>Chair: Professor Miya, Visiting Professor at Hosei University Graduate School</li> </ul> </li> <li><b>2) Evaluation of seismic safety standards at the plant in light of outcomes from the Chuetsu-Oki earthquake</b> <ul style="list-style-type: none"> <li>&gt;&gt; Existing sub-committee on seismic safety and structural design</li> <li>Chair: Professor Abe, Emeritus Professor at Tokyo University</li> </ul> </li> <li><b>3) Operational management and equipment and facility safety at the plant at the time of the Chuetsu-Oki earthquake and future strategies</b> <ul style="list-style-type: none"> <li>&gt;&gt; Working Group on operational management and equipment safety assessment (provisional title)</li> <li>Chair: Professor Sekimura from Tokyo University Graduate School</li> </ul> </li> </ol>
----------------------------	---	--