

## Report on the impact of the Niigata-Chuetsu-Oki Earthquake on the Kashiwazaki-Kariwa Nuclear Power Station and response by Tokyo Electric Power Company (TEPCO), national and local governments and other bodies (as at July 23, 2007)

Date	TEPCO and other power utilities and JANTI (Japan Nuclear Technology Institute)	National and local government																
Monday July 16, 2007	<p><b>10:13 approx. Earthquake occurs</b></p> <p><b>TEPCO press release: Earthquake update (as at 1 p.m.)</b></p> <ul style="list-style-type: none"> <li>• Kashiwazaki-Kariwa nuclear plant reactors 2, 3, 4 and 7 scrambled automatically. Reactors 1, 5 and 6 were already shut down for periodical inspection.</li> <li>• <b>The fire department confirmed that a fire in the transformer of the No. 3 reactor was brought under control (12:10 p.m.)</b></li> <li>• There is no environmental impact from the earthquake and associated fire.</li> </ul>																	
	<p><b>TEPCO press release: Earthquake update (as at 6:30 p.m.)</b></p> <ul style="list-style-type: none"> <li>• Several aftershocks were recorded but did not affect any sections of the plant</li> <li>• All sections were checked for Departure from Limiting Condition of Operation (LCO) <ul style="list-style-type: none"> <li>- Reactors 1, 2 and 3: low water level in spent fuel pool (violation rectified)</li> <li>- Reactor 3: Reactor building blow-out panel removed (investigation of violation continuing)</li> <li>- Reactors 4, 5, 6 and 7: no violations</li> </ul> </li> </ul>																	
	<p><b>Seismic observation records at the plant (preliminary data)</b></p> <ul style="list-style-type: none"> <li>• Recorded earthquake movement provisional values for foundation mat at lowest part of reactor building (with design acceleration response at the same location shown in brackets), in gal</li> </ul> <table border="1" style="margin-left: 20px;"> <thead> <tr> <th>Recorded</th> <th>No. 1 reactor</th> <th>No. 5 reactor</th> <th>No. 6 reactor</th> </tr> </thead> <tbody> <tr> <td>Horizontal (N-S)</td> <td>311(274)</td> <td>277(249)</td> <td>271(263)</td> </tr> <tr> <td>Horizontal (E-W)</td> <td>680(273)</td> <td>442(254)</td> <td>322(263)</td> </tr> <tr> <td>Vertical</td> <td>408(235)</td> <td>205(235)</td> <td>488(235)</td> </tr> </tbody> </table>	Recorded	No. 1 reactor	No. 5 reactor	No. 6 reactor	Horizontal (N-S)	311(274)	277(249)	271(263)	Horizontal (E-W)	680(273)	442(254)	322(263)	Vertical	408(235)	205(235)	488(235)	<p><b>Directives from Director of Nuclear and Industrial Safety Agency (NISA) to TEPCO: Analyze seismic observation data and determine impact on earthquake resistance</b></p> <ul style="list-style-type: none"> <li>• <b>Directed to base the report on the fact that the maximum seismic acceleration recorded at Unit 1, 5 and 6 exceeded the maximum response acceleration</b> based on the base level of seismic motion</li> <li>• Analyze seismic observation data from the earthquake</li> <li>• Check whether the earthquake has compromised safety of key equipment and facilities</li> </ul>
	Recorded	No. 1 reactor	No. 5 reactor	No. 6 reactor														
Horizontal (N-S)	311(274)	277(249)	271(263)															
Horizontal (E-W)	680(273)	442(254)	322(263)															
Vertical	408(235)	205(235)	488(235)															
<p><b>TEPCO press release: Leakage of radioactive matter from Unit 6</b></p> <ul style="list-style-type: none"> <li>• Confirmation of water leakage in uncontrolled areas on 3<sup>rd</sup> level and mid 3<sup>rd</sup> level of reactor chamber (12:50)</li> <li>• Confirmation of radiation in water (18:20)</li> <li>• Volume of water leak: 3rd level = 0.6 l, approx 2.8 x 10<sup>2</sup> Bq; mid 3rd level = 0.9 l, approx 1.6 x 10<sup>4</sup> Bq</li> <li>• <b>The water then flowed out to the sea via a discharge outlet (approx. 1.2 m<sup>3</sup>, 6 x 10<sup>4</sup> Bq)</b></li> <li>• <b>Water is no longer reaching the sea. No significant change in sea level monitor reading, which is below the legislated value</b></li> </ul>	<p><b>Directives from Director of NISA to power utilities: directives to power companies affected by fire and radiation leak</b></p> <ul style="list-style-type: none"> <li>• <b>Directions to power companies in receipt of directives from the METI Minister regarding unacceptable delays in launching fire-fighting response and in communicating the radiation leak to NISA</b> at the Kashiwazaki-Kariwa nuclear plant</li> <li>• Inspection and report on fire-fighting procedures for fires at the nuclear plant</li> <li>• Review and report on organization of communication structure between nuclear plant and head office and between head office and the relevant government authorities in regards to incidents such as radiation leaks</li> </ul>																	
Tuesday 17 July		<p><b>NISA press release: Leakage of radioactive material from Unit 6</b></p> <p>NISA response to the report from TEPCO dated July 16 regarding radioactive leak from Unit 6</p> <ul style="list-style-type: none"> <li>• <b>NISA inspectors confirmed that discharge of radioactive water had ceased, and vindicated TEPCO's original outlook</b></li> <li>• TEPCO was ordered to maintain a strict program of monitoring for leakage in the surrounding surveillance area; to put in place a rigid reporting structure; and to identify and rectify the causes</li> </ul>																
	<p><b>TEPCO press release: iodine and other substances detected from main exhaust stack of Unit 7</b></p> <ul style="list-style-type: none"> <li>• At approximately 1:00 p.m., <b>iodine and radioactive particulate matter (Cr-51, Co-60) were detected during regular observation of the main exhaust stack</b></li> <li>• Total radiation was 3 x 10<sup>8</sup> Bq, dosage was approximately 1.1 x 10<sup>-7</sup> mSv, <b>well below the legally prescribed maximum (1 mSv per individual)</b></li> <li>• No significant changes in the main air stack radiation monitor or monitoring post</li> <li>• Other exhaust stacks will be monitored</li> </ul>	<p><b>NISA press release: Iodine detected in main air stack of Unit 7</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• Cause unknown. Potential causal relationship with earthquake unclear. NISA to launch full investigation</li> </ul>																
	<p><b>TEPCO press release: Earthquake update (as at 5:00 p.m.)</b></p> <p>Unit 1: 8 incidents including: oil leak from exciter transformer (minimal, ongoing); <b>water puddle under damaged fire-fighting pipes (1,670 m<sup>3</sup>)</b></p> <p>Unit 2: 7 incidents including: oil leaking from flange under main transformer (ongoing)</p> <p>Unit 3: 5 incidents including: <b>fire in 3B house transformer (brought under control)</b></p> <p>Unit 4: 3 incidents including: misaligned connecting ducts on main exhaust stack</p> <p>Unit 5: 4 incidents including: water leaking from No. 4 filtrate water tank</p> <p>Unit 6: 3 incidents including: oil leak from low-start transformer B (minimal, ongoing)</p> <p>Unit 7: 3 incidents including: cracks in joints of reinforcement along inlet channel embankment (up to 8 cm in size)</p> <p>Switch yard: 3 incidents including: 500 kV New Niigata 2L shut down</p> <p>Solid waste storage warehouse: <b>Around 100 drums toppled (some with lids open)</b></p> <p>Administration office building: 2 incidents including: normal power supplies shut down</p> <p>Site/other: Seven incidents including: damage to fire-fighting equipment in four locations; water leaks</p>	<p><b>NISA press release: earthquake update</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• Council member Kato has today <b>dispatched four more NISA officials</b> to work alongside the inspectors at the site</li> <li>• <b>TEPCO findings that iodine detected in the main exhaust stack of the Unit 7 has no impact on the surrounding environment were accepted</b></li> <li>• <b>All values detected at the main exhaust stacks of Unit 1 through 6 were below the minimum requirements</b></li> <li>• Instructed to immediately assess the situation with toppled solid waste drums</li> </ul>																

Wednesday 18 July	<p><b>TEPCO press release: Amendment to notification of radiation leak from Unit 6 (dated 16 July)</b></p> <ul style="list-style-type: none"> <li>Discharge out to sea: Amended from <math>6 \times 10^4</math> Bq to <math>9 \times 10^4</math> Bq</li> </ul>	<p><b>NISA press release: Radiation leak from Unit 6</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO as per amendment</li> <li>TEPCO still maintains that the three-month radioactivity concentration in the surrounding surveillance area is less than 2 in 10 billion Bq/cm<sup>3</sup>, due to dilution of radioactive matter. <b>This figure is a billion times less than the maximum allowable discharge concentration in the surrounding surveillance area over three months (0.2 Bq/cm<sup>3</sup>).</b></li> <li>The error in the announcement on the 16<sup>th</sup> was extremely regrettable</li> <li>A full investigation will be conducted into the source of the calculation error. Faster and more rigorous reporting was ordered.</li> </ul>																																
	<p><b>TEPCO press release: Earthquake update (as at 5:00 p.m.)</b></p> <p>Unit 1 = 9 incidents, Unit 2 = 9 incidents, Unit 3 = 8 incidents, unit 4 = 4 incidents, Unit 5 = 4 incidents, Unit 6 = 3 incidents, Unit 7 = 5 incidents, Switch yard = 3 incidents, Solid waste storage warehouse = 1 issue, Administration office building = 2 incidents, Site/others = 9 incidents</p> <ul style="list-style-type: none"> <li>Observations of the concentration of radioactive matter in the air in the solid waste storage warehouse were taken at four locations. <b>No radioactive matter was detected. Approximately 16 l of water had leaked from the toppled drums, but no radiation was detected. Inspection is continuing</b></li> </ul>	<p><b>NISA press release: Earthquake update</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Investigations by Mr. Kato and inspectors at the plant are continuing</li> <li><b>Confirmation that radioactive water did not leak from toppled drums</b></li> <li>As yet, no significant directives confirmed for main air stack radiation monitor and monitoring posts</li> </ul> <p><b>Mayor of Kashiwazaki, Hiroshi Aida</b></p> <ul style="list-style-type: none"> <li>Issued direction of <b>emergency prohibition of use of some facilities for all Units at the plant (in relation to dangerous facilities such as outdoor tanks)</b>, in accordance with the Fire Services Law</li> </ul>																																
Thursday 19 July	<p><b>TEPCO press release: Seismic observation records at K-K NPS (subsequent to preliminary data released 16 July)</b></p> <ul style="list-style-type: none"> <li>Data for the earthquake has been collected from all Units</li> <li>Seismic acceleration observations measured at foundation mat at lowest part of reactor building (with design acceleration response at the same location shown in brackets), in gal</li> </ul> <table border="1" data-bbox="311 871 1573 1081"> <thead> <tr> <th>Recorded</th> <th>Unit 1</th> <th>Unit 2</th> <th>Unit 3</th> <th>Unit 4</th> <th>Unit 5</th> <th>Unit 6</th> <th>Unit 7</th> </tr> </thead> <tbody> <tr> <td>Horizontal (N-S)</td> <td>311(274)</td> <td>304(167)</td> <td>308(192)</td> <td>310(193)</td> <td>277(249)</td> <td>271(263)</td> <td>267(263)</td> </tr> <tr> <td>Horizontal (E-W)</td> <td>680(273)</td> <td>606(167)</td> <td>384(193)</td> <td>492(194)</td> <td>442(254)</td> <td>322(263)</td> <td>356(263)</td> </tr> <tr> <td>Vertical</td> <td>408(235)</td> <td>282(235)</td> <td>311(235)</td> <td>337(235)</td> <td>205(235)</td> <td>488(235)</td> <td>355(235)</td> </tr> </tbody> </table> <p><b>TEPCO press release: plant status (as at 5:00 p.m.)</b></p> <p>All facilities have been inspected externally where possible. The results are as follows:</p> <ul style="list-style-type: none"> <li>Reactors 2, 3, 4 and 7 shut down automatically and are now stable in cold shutdown</li> <li>Two incidents involving radioactivity emission <ul style="list-style-type: none"> <li><u>1) Water leak from Unit 6 discharged into the open seas (July 16 press release)</u> <ul style="list-style-type: none"> <li>Level of radiation discharged into the sea was approximately <math>9 \times 10^4</math> Bq; <b>total radiation exposure was approximately <math>2 \times 10^{-9}</math> mSv (well below the legally prescribed maximum of 1 mSv per individual per year)</b></li> <li>The SF pool water that flooded into the operating floor of the reactor chamber (a controlled area) is thought to have made its way into the uncontrolled area along the fuel exchanger cables and wire ducts. The cause is still under investigation.</li> </ul> </li> <li><u>2) Iodine and radioactive particulate matter detected in main exhaust stack monitor of No. 7 reactor (July 17 press release)</u> <ul style="list-style-type: none"> <li>Radiation level detected thus far from the main air stack is approximately <math>4 \times 10^8</math> Bq; <b>total radiation exposure was approximately <math>2 \times 10^{-7}</math> mSv (well below the legally prescribed maximum of 1 mSv per individual per a year)</b></li> <li>Evaluation of radiation levels continuing</li> </ul> </li> </ul> </li> <li>Main findings identified thus far: <ul style="list-style-type: none"> <li>14 incidents involving radioactive matter: the 2 incidents described above, misaligned connecting ducts on main exhaust stack (Unit 1 through 5), water puddle under damaged fire-fighting pipes (1,670 m<sup>3</sup>) (Unit 1), water on operating floor in reactor building (Unit 1 through 6)</li> <li>53 incidents not involving radioactive matter</li> </ul> </li> </ul>	Recorded	Unit 1	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6	Unit 7	Horizontal (N-S)	311(274)	304(167)	308(192)	310(193)	277(249)	271(263)	267(263)	Horizontal (E-W)	680(273)	606(167)	384(193)	492(194)	442(254)	322(263)	356(263)	Vertical	408(235)	282(235)	311(235)	337(235)	205(235)	488(235)	355(235)	<p><b>Nuclear Safety Commission</b></p> <ol style="list-style-type: none"> <li>Findings from site investigation</li> <li>Impact on the nuclear power station</li> <li>Outbreak of fire in the transformer at Unit 3 and subsequent response</li> </ol> <p><b>&lt;Findings from site investigation&gt;</b></p> <ol style="list-style-type: none"> <li>Investigation conducted by three officials, including acting Chairman Higashi and Mr. Hayata</li> <li>Sites visited: Unit 3 house transformer (fire outbreak), Unit 2 transformer (damage to foundation bolts), No. 6 reactor exhaust stack area (water leak), control room for Unit. 6 and 7, solid waste storage warehouse</li> <li>Observations from Mr. Higashi: <ul style="list-style-type: none"> <li>The No. 7 reactor scram automatically at the time of the earthquake. <b>A readout in the central control room of indicated that the reactor is under cold shutdown. Operators will need to continue checking the reactor core.</b></li> <li>The response to the fire in the transformer at Unit 3 at the time of the earthquake constitutes a key issue. <b>It is important that the lessons learned from this incident are passed on to other power stations.</b></li> <li>Water containing trace levels of radiation spilled from the spent fuel pool of the No. 6 reactor due to major tremors during the earthquake, and also because containment did not function adequately. We were told that it may have reached the uncontrolled area</li> </ul> </li> </ol> <p><b>&lt;Statement from Chairperson Atsuyuki Suzuki&gt;</b></p> <ul style="list-style-type: none"> <li>The power plant is essentially safe. It did not reach a serious state. All operating reactors scrambled automatically as they were designed to do, and the key safety features providing multiple layers of protection from highly radioactive material inside the reactor functioned properly. Nevertheless, the earthquake has had a significant impact on the plant, as exemplified by the transformer fire.</li> <li>The radioactive water leak into the uncontrolled area will be investigated based on reports from operators and government authorities as well as the findings of the Nuclear Safety Commission.</li> <li>According to the Nuclear Safety Commission findings, there are many lessons learned from the transformer fire, with respect to procedures at other nuclear plants and fire-fighting techniques in general. The necessary studies should be carried out as soon as practicable in order to identify the salient issues.</li> <li><b>We have put in a strong request to the government authorities to instruct the operators to evaluate the impact of the earthquake on the seismic resistance of the plant. The operators will also be asked to perform additional studies to identify the location of the fault line.</b></li> <li>We will lobby the operators and the government authorities for a thorough investigation in line with the newly amended guidelines with respect to the suitability of the original design and the emergence of new knowledge which was not available at the time.</li> <li><b>We believe that the back check will demonstrate the validity of the new guidelines for the recent earthquake. Now is not the time to debate the pros and cons of further amendments to the new guidelines. The validity depends on whether the requirements are adequate. We must not make any assumptions.</b></li> </ul> <p><b>NISA press release: Earthquake update</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li>Mr. Kato and inspectors at the plant reported <b>no problems with reactor vessels and associated equipment and machinery</b> based on visual inspection</li> <li>As yet, no significant directives confirmed for main air stack radiation monitor and monitoring posts</li> </ul>
Recorded	Unit 1	Unit 2	Unit 3	Unit 4	Unit 5	Unit 6	Unit 7																											
Horizontal (N-S)	311(274)	304(167)	308(192)	310(193)	277(249)	271(263)	267(263)																											
Horizontal (E-W)	680(273)	606(167)	384(193)	492(194)	442(254)	322(263)	356(263)																											
Vertical	408(235)	282(235)	311(235)	337(235)	205(235)	488(235)	355(235)																											

	<p><b>TEPCO press release: Update on investigation into iodine detected in main exhaust stack of Unit 7</b>          &lt;Origin of iodine discharge into the environment&gt;</p> <ul style="list-style-type: none"> <li>• Delay to shut off turbine ground exhaust ventilator after automatic reactor scram</li> <li>• As a result, residual iodine and radioactive particulate matter in the condenser was sucked into the exhaust ventilator and discharged via the exhaust stack. The investigation is continuing.</li> <li>• Analysis of reactor water samples indicates that there was no leakage of radioactive matter from the fuel rods into the reactor water</li> </ul> <p>&lt;Environmental impact&gt;</p> <ul style="list-style-type: none"> <li>• The monitoring frequency for radioactive iodine and particulate matter in the main exhaust stack has been increased from once per week to daily. Atmospheric monitoring in the surrounding surveillance area is also being conducted daily as of July 18 onwards.</li> <li>• Iodine 131 and iodine 133 were detected in the main exhaust stack on July 18, but were not detected in the surrounding surveillance area on July 18 or 19.</li> <li>• The total radiation dose from the main air stack thus far is approximately <math>2 \times 10^{-7}</math> mSv</li> </ul>	<p><b>NISA press release: iodine detected in main exhaust stack of Unit 7 (the second report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers are currently confirming iodine emissions from air stack and reactor water measurements</li> <li>• TEPCO to be instructed to take necessary actions with respect to emission controls</li> </ul>
Friday July 20	<p><b>TEPCO press release: Results of radiation readings from main exhaust stack of Unit 7</b>          Environmental impact</p> <ul style="list-style-type: none"> <li>• Iodine 131 and iodine 133 were detected in the main air stack on July 18, but not on July 19.</li> <li>• The total radiation dose from the main exhaust stack thus far is approximately <math>2 \times 10^{-7}</math> mSv (no change from July 19)</li> <li>• Monitoring for iodine and radioactive matters in the main exhaust stack will be conducted on a daily basis for the immediate future</li> </ul> <p><b>TEPCO press release: Earthquake update (as at 1:00 p.m.)</b>          63 issues confirmed to date (not including the four automatic reactor scrams at the time of the earthquake)</p> <ol style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)             <ul style="list-style-type: none"> <li>- Discharge of water containing radioactive material out to sea (Unit 6)</li> <li>- Iodine and radioactive particulates detected at main exhaust stack monitor (Unit 7)</li> <li>- Misaligned connecting ducts on main exhaust stack (Unit 1 through 5)</li> <li>- Water puddle in combined reactor building from damaged fire-fighting pipes (1,670 m<sup>3</sup>) (Unit 1)</li> <li>- Water puddle on operating floor in reactor building (Unit 1 through 7)</li> </ul> </li> <li>2) Incidents NOT related radioactive materials (52 issues, including the four automatic reactor scram at the time of the earthquake)</li> </ol>	<p><b>NISA press release: Iodine detected in main exhaust of Unit 7 (the third report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers at the plant are currently checking over data for iodine discharge from the air shaft and reactor water measurements. NISA will continue to monitor the situation strictly</li> </ul> <p><b>NISA press conference: Earthquake update (the fourth report)</b></p> <ul style="list-style-type: none"> <li>• Information received from TEPCO (see left)</li> <li>• NISA officers are currently at the plant:             <ul style="list-style-type: none"> <li>- The data demonstrates that there was no radiation in the collected water that was discovered on the 5<sup>th</sup> floor below ground of the reactor combined building, which had come from damaged fire-fighting pipes in the Unit 1.</li> <li>- Observations data shows that iodine and particulates were not detected in the main exhaust stack of the Unit 7 on July 18 and 19.</li> <li>- NISA officers are present at the TEPCO investigation into the route taken by the water leak in the uncontrolled area of the No. 6 reactor to determine whether TEPCO's assumptions were correct</li> </ul> </li> <li>• There are no significant changes in the main air stack radiation monitor and monitoring posts</li> </ul>

	<p><b>TEPCO press conference: Investigation into fire in the house transformer 3B at Unit 3</b>  Inspection involved mainly above-ground inspection and found the following:</p> <ul style="list-style-type: none"> <li>• The connecting bus line section on secondary side of the transformer had slipped downwards relative to the transformer foundations</li> <li>• The transformer and the connecting bus line on the secondary side are out of vertical alignment</li> <li>• Oil is leaking from the bushing on the transformer secondary side</li> <li>• The fire has caused extensive damage to the connecting ducts of the connecting bus line section on the transformer secondary side; the bus line section is melted and broken in some places</li> <li>• There does not appear to have been any other serious fire-related damage to date</li> </ul> <p><b>TEPCO press release: Reporting on safety levels</b>  Internal investigations are continuing in accordance with the directive from NISA dated July 16. A report of the findings, covering the events, causes and responses, will be submitted to NISA, and preventative measures will be implemented as soon as practicable.  &lt;NISA directive dated July 16&gt;</p> <ol style="list-style-type: none"> <li>1) Investigation of causes why it took so long to deliver the report on the water leakage</li> <li>2) Confirm the response to a transformer fire</li> <li>3) Analyze seismic observation data from the earthquake and check safety (seismic resistance) of key equipment and facilities</li> </ol> <p><b>Power utilities: Report on findings of review of fire-fighting and incident communicating procedures and structures</b>  <b>Report to NISA in response to</b> written directive from NISA dated July 16  &lt;Summary of directive&gt;</p> <ol style="list-style-type: none"> <li>1) Report on an immediate review of fire-fighting procedures and structures in response to the fire at the nuclear power plant</li> <li>2) Report on an immediate review of the communication structure between nuclear plant and head office and between head office and the relevant government authorities in regards to incidents such as radiation leaks</li> </ol>	<p><b>Directive from METI minister to power utilities</b>  Stipulates measures required in order to ensure the safety and security of the people. Details of planned modifications/upgrades in accordance with 1) and 2) below must be submitted by July 26.</p> <p><u>1) Upgrade to internal fire-fighting capacity</u></p> <ul style="list-style-type: none"> <li>• Move immediately to put in place a structure designed to facilitate immediate deployment of staff in sufficient numbers in the event of a fire</li> <li>• Maintain chemical fire-fighting vehicles and other equipment required for oil fires</li> <li>• Provide dedicated communication lines for fire-fighting activities</li> <li>• Provide the relevant employees with more opportunity to work closely with fire-fighting services, such as taking part in drills and exercises</li> </ul> <p><u>2) Faster and more rigorous incident communication procedures</u></p> <ul style="list-style-type: none"> <li>• Move immediately to put in place a structure for immediate deployment of staff to check for radioactive leakage in the event of a fire due to earthquake or other cause</li> <li>• Set up robust communication lines designed to withstand the effects of a fire due to earthquake or other cause and enable internal communication and communication between the plant and the emergency headquarters set up by the operator</li> <li>• Inform local and national governments immediately of any confirmed or suspected leakage of radioactive material</li> </ul> <p><u>3) Check earthquake resistance with a view to public safety</u></p> <ul style="list-style-type: none"> <li>• Incorporate new information and insights gained from this incident into ongoing evaluation of earthquake resistance and facility safety levels</li> <li>• Review of the implementation program in order to complete the evaluation as quickly as possible (findings should be made available within one month)</li> </ul> <p><b>METI minister: non-scheduled press conference</b></p> <ul style="list-style-type: none"> <li>• Notwithstanding peripheral facilities and equipment, the key reactors themselves all shut down safely and automatically as designed</li> <li>• Radioactive emissions from the power plant were detected; emissions from the Unit 7 main exhaust stack had ceased as of today. The volume of radiation generated thus far is equivalent to one part in ten million of the volume of radiation that an average person would absorb from natural sources during normal daily activities. Similarly, the radioactive water that leaked from the Unit 6 is equivalent to nine liters of hot water from a radon thermal spring, and will have no impact on the surrounding environment.</li> </ul>
--	--	---

<p>Saturday July 21</p>	<p><b>TEPCO</b>  ·Site open to press (Unit 1 Diesel Oil Tank, Unit 3 House Transformer, No.4 Filtered Water Tank and etc.)</p> <p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>• 63 issues confirmed to date (not including the four automatic reactor scrams at the time of the earthquake): <b>no additions since July 20</b> <ol style="list-style-type: none"> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor scram due to the earthquake)</li> </ol> </li> <li>• An analysis of reactor water from reactors 2 through 7, which were loaded with fuel, indicated no damage to the fuel. It is considered highly unlikely that fuel was damaged by the release of radioactive iodine, for several reasons: the iodine 131 concentration inside the No. 7 reactor was normal at around <math>3 \times 10^{-2}</math> Bq/g during operation; after shutdown it fell to <math>9 \times 10^{-3}</math> Bq/g, according to analysis of reactor water samples; and the high-sensitivity off-gas monitor reading declined after the emergency shutdown due to the earthquake.</li> <li>• Summary of increased monitoring for radioactive emissions from the main exhaust stack of Unit 7  &lt;Radioactive iodine and particulate emissions from the main exhaust stack of Unit 7&gt;</li> </ul> <table border="1" data-bbox="385 1407 1424 1596"> <thead> <tr> <th>Sampling period</th> <th>Radioactive iodine</th> <th>Particulate matter</th> </tr> </thead> <tbody> <tr> <td>July 9 – 17</td> <td><math>3 \times 10^8</math> Bq</td> <td><math>2 \times 10^6</math> Bq</td> </tr> <tr> <td>July 17 – 18</td> <td><math>2 \times 10^7</math> Bq</td> <td>Not detected</td> </tr> <tr> <td>July 18 – 19</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>July 19 – 20</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>Total</td> <td><math>4 \times 10^8</math> Bq</td> <td><math>2 \times 10^6</math> Bq</td> </tr> </tbody> </table> <p>&lt;Radioactive iodine and particulate levels at boundaries of surrounding surveillance area&gt;</p> <table border="1" data-bbox="385 1617 1602 1764"> <thead> <tr> <th rowspan="2">Sampling period</th> <th colspan="2">MP-1</th> <th colspan="2">MP-5</th> <th colspan="2">MP-8</th> </tr> <tr> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> </tr> </thead> <tbody> <tr> <td>July 18 – 20</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>July 21</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> </tr> </tbody> </table>	Sampling period	Radioactive iodine	Particulate matter	July 9 – 17	$3 \times 10^8$ Bq	$2 \times 10^6$ Bq	July 17 – 18	$2 \times 10^7$ Bq	Not detected	July 18 – 19	Not detected	Not detected	July 19 – 20	Not detected	Not detected	Total	$4 \times 10^8$ Bq	$2 \times 10^6$ Bq	Sampling period	MP-1		MP-5		MP-8		Iodine	Particulates	Iodine	Particulates	Iodine	Particulates	July 18 – 20	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	July 21	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	
Sampling period	Radioactive iodine	Particulate matter																																													
July 9 – 17	$3 \times 10^8$ Bq	$2 \times 10^6$ Bq																																													
July 17 – 18	$2 \times 10^7$ Bq	Not detected																																													
July 18 – 19	Not detected	Not detected																																													
July 19 – 20	Not detected	Not detected																																													
Total	$4 \times 10^8$ Bq	$2 \times 10^6$ Bq																																													
Sampling period	MP-1		MP-5		MP-8																																										
	Iodine	Particulates	Iodine	Particulates	Iodine	Particulates																																									
July 18 – 20	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																																									
July 21	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																																									

Sunday July 22	<p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>63 issues confirmed to date (not including the four automatic reactor scrams due to the earthquake): <b>no additions since July 20</b></li> </ul> <p>&lt;Radioactive iodine and particulate emissions from No. 7 reactor air stack&gt;</p> <table border="1"> <thead> <tr> <th>Sampling period</th> <th>Radioactive iodine</th> <th>Particulate matter</th> </tr> </thead> <tbody> <tr> <td>July 20 – 21</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>Total (July 9 – 21)</td> <td>4 x 10<sup>8</sup> Bq</td> <td>2 x 10<sup>6</sup> Bq</td> </tr> </tbody> </table> <p>&lt;Radioactive iodine and particulate levels at boundaries of surrounding surveillance area&gt;</p> <table border="1"> <thead> <tr> <th rowspan="2">Sampling period</th> <th colspan="2">MP-1</th> <th colspan="2">MP-5</th> <th colspan="2">MP-8</th> </tr> <tr> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> <th>Iodine</th> <th>Particulates</th> </tr> </thead> <tbody> <tr> <td>July 22</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> <td>Not detected</td> </tr> </tbody> </table>	Sampling period	Radioactive iodine	Particulate matter	July 20 – 21	Not detected	Not detected	Total (July 9 – 21)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	Sampling period	MP-1		MP-5		MP-8		Iodine	Particulates	Iodine	Particulates	Iodine	Particulates	July 22	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected	<p><b>Governor of Niigata Prefecture Hirohiki Izumida</b></p> <ul style="list-style-type: none"> <li>Submits written request to national government regarding investigation by IAEA group</li> <li>“This incident has damaged local industry through rumor-mongering. In order to restore public confidence, <b>we must provide the outside world with full and accurate information</b>”</li> </ul>
Sampling period	Radioactive iodine	Particulate matter																													
July 20 – 21	Not detected	Not detected																													
Total (July 9 – 21)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																													
Sampling period	MP-1		MP-5		MP-8																										
	Iodine	Particulates	Iodine	Particulates	Iodine	Particulates																									
July 22	Not detected	Not detected	Not detected	Not detected	Not detected	Not detected																									
Monday July 23	<p><b>TEPCO press release: Radiation measurements at the main exhaust stack of Unit 7 for July 22</b></p> <p>&lt;Radioactive iodine and particulate emissions from No. 7 reactor air stack&gt;</p> <table border="1"> <thead> <tr> <th>Sampling period</th> <th>Radioactive iodine</th> <th>Particulate matter</th> </tr> </thead> <tbody> <tr> <td>July 21 – 22</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>Total (July 9 – 22)</td> <td>4 x 10<sup>8</sup> Bq</td> <td>2 x 10<sup>6</sup> Bq</td> </tr> </tbody> </table> <p><b>TEPCO press release: Earthquake update (as at 3:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>63 issues confirmed to date (not including the four automatic reactor scrams due to the earthquake): <b>no additions since July 20</b></li> <li>1) Incidents related to radioactive materials (15 issues)</li> <li>2) Incidents NOT related to radioactive materials (52 issues, including the four automatic reactor scrams due to the earthquake)</li> <li><b>The amount of puddle on the 5<sup>th</sup> floor below ground of the reactor combined building. 1,670m<sup>3</sup> ==&gt; 2,000m<sup>3</sup></b></li> <li><b>Radiation was not detected during regular testing for radioactive emissions at the main exhaust stacks of the Unit 1, 2 and 6. Unit 3, 4 and 5 will be tested tomorrow.</b></li> </ul> <p><b>TEPCO press release: Investigation into leakage of radioactive matter in Unit 6</b></p> <p>Following a thorough investigation, <b>the water leak in the uncontrolled areas on the 3<sup>rd</sup> and mid 3<sup>rd</sup> levels of the reactor building was attributed to the following factors.</b></p> <ul style="list-style-type: none"> <li>Water overflowed from the spent fuel pool on the operating floor on the 4<sup>th</sup> level of the reactor building and entered the fuel exchanger power supply box on the same floor, where it got into a cable duct via gaps in the seal around the cable passages in the box.</li> <li>The water traveled through embedded the cable duct, and dripped from upper air conditioning ducts on the mid 3<sup>rd</sup> level of the reactor building. It also dripped from openings in the mid 3<sup>rd</sup> level floor down to the 3<sup>rd</sup> level floor.</li> <li>Puddle on the 3<sup>rd</sup> level floor surface drained out through drain outlets into a non-radioactive wastewater tank in the basement level. From here, it was sent out to sea via discharge outlets</li> </ul> <p><b>JANTI: On-site investigation (the team of 3 members) — until 24 July</b></p>	Sampling period	Radioactive iodine	Particulate matter	July 21 – 22	Not detected	Not detected	Total (July 9 – 22)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	<p><b>NISA press release: Earthquake update (the fifth report)</b></p> <ul style="list-style-type: none"> <li>Information received from TEPCO (see left)</li> <li><b>NISA Chairman Mr. Komoda visited Niigata prefecture today and met with the governor of Niigata prefecture, the mayor of Kashiwazaki City and the mayor of Kariwa town to discuss the NISA response to the incident</b></li> <li>NISA officers are currently at the plant: <ul style="list-style-type: none"> <li>The data demonstrates that no iodine or particulates have been detected in the main air stack of the No. 7 since July 18.</li> <li>With respect to the leakage of radioactive material from the Nos. 6 and 7 reactors, NISA will be present at the TEPCO investigation into the route taken by the water leak to determine whether the suspected route initially announced by TEPCO was correct</li> </ul> </li> <li>There are no significant changes in the main air stack radiation monitor and monitoring posts</li> </ul> <p><b>METI Vice Minister, Kitabatake: regular press conference</b></p> <ul style="list-style-type: none"> <li><b>In light of the growth of nuclear power throughout the world, it is most important to provide safety information about nuclear power around the world via the medium of the IAEA, and to share information about strategies and initiatives.</b> To this end, <b>the Ministry has formally notified the IAEA today</b> that its staffs will be permitted to visit the Kashiwazaki-Kariwa nuclear power plant in Japan.</li> </ul>																				
Sampling period	Radioactive iodine	Particulate matter																													
July 21 – 22	Not detected	Not detected																													
Total (July 9 – 22)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																													
Tuesday July 24	<p><b>TEPCO press release: Radiation readings at the main exhaust stack of the Unit 7 for July 23</b></p> <p>Radioactive iodine and particulate emissions from Unit 7 main exhaust stack</p> <table border="1"> <thead> <tr> <th>Sampling period</th> <th>Iodine</th> <th>Particulates</th> </tr> </thead> <tbody> <tr> <td>July 22 – 23</td> <td>Not detected</td> <td>Not detected</td> </tr> <tr> <td>Total (July 9 – 23)</td> <td>4 x 10<sup>8</sup> Bq</td> <td>2 x 10<sup>6</sup> Bq</td> </tr> </tbody> </table> <p><b>TEPCO press release: Earthquake update (as at 2:00 p.m.)</b></p> <ul style="list-style-type: none"> <li>In addition to the 63 issues confirmed to date (which excludes the four automatic reactor scrams at the earthquake), <b>we have confirmed damage to drive shaft joints on a ceiling crane in the No. 6 reactor building</b></li> <li><b>Radiation monitoring in the main exhaust stack was conducted at Unit 3, 4 and 5 but no radioactive material was detected</b></li> </ul>	Sampling period	Iodine	Particulates	July 22 – 23	Not detected	Not detected	Total (July 9 – 23)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq	<p><b>Minister of Economy, Trade and Industry Akira Amari: press conference following Cabinet meeting</b></p> <ol style="list-style-type: none"> <li>Committee set up to investigate effect of the Chuetsu offshore earthquake on the nuclear power plant <ul style="list-style-type: none"> <li>The Committee, <b>acting from the perspective of a third party, will conduct an in-depth examination of the background to incidents</b> such as the transformer fire and emissions of radioactive materials from the power plant, and will <b>use this to identify future issues to be addressed by the national government and operators of nuclear plants.</b> The Committee will be headed by Professor Haruki Madarame from Tokyo University, and will report to the Nuclear Safety and Security Chapter of the Resources and Energy Study Group</li> </ul> </li> <li>IAEA delegation <ul style="list-style-type: none"> <li>Last week the IAEA requested access for a joint study mission. Our response is that <b>Japan believes the international sharing of information to be beneficial</b></li> <li><b>Proposals from Japan:</b> <ul style="list-style-type: none"> <li>IAEA delegation will be permitted to investigate the site</li> <li>The incident will be discussed at the IAEA General Conference in September with senior officials from regulatory bodies around the world</li> <li>Japan will host an international workshop composed of expert consultants from around the world</li> </ul> </li> </ul> </li> </ol> <ul style="list-style-type: none"> <li>We will continue to release information about the impact on the nuclear power plant <b>in clear and simple language in order to restore the confidence of local communities</b></li> </ul>																				
Sampling period	Iodine	Particulates																													
July 22 – 23	Not detected	Not detected																													
Total (July 9 – 23)	4 x 10 <sup>8</sup> Bq	2 x 10 <sup>6</sup> Bq																													